



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

November 16, 1979

Mr. Boyce H. Grier, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: LER 79-021/03L-0, omission of testing standby auxiliary
feedwater pump crossover valves
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Grier:

In accordance with Technical Specifications, Article 6.9.2.b.(3)
observed inadequacies in the implementation of administrative or procedural
controls which threaten to cause reduction of degree of redundancy provided
in reactor protection systems or engineered safety feature systems, the
attached Licensee Event Report LER 79-021/03L-0 is hereby submitted.
Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.

Attachment

cc: Mr. Victor Stello, Jr. (30)
Mr. Norman R. Haller (3)

7911200 402

Approved
5/11

5

