




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

HARRY G. SADDOCK  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700



July 29, 1980

Mr. Boyce H. Grier, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: IE Bulletin No. 80-16, Potential Misapplication of Rose-  
mount Inc. Models 1151 and 1152 Pressure Transmitters  
with Either "A" or "D" Output Codes  
R. E. Ginna Nuclear Power Plant, Unit #1  
Docket No. 50-244

Dear Mr. Grier:

In reply to Inspection and Enforcement Bulletin 80-16, dated  
June 27, 1980, concerning potential misapplication of pressure  
transmitters, there are no Rosemount Inc. Models 1151 and 1152  
pressure transmitters installed or planned for use in any safety-  
related application at Ginna Station.

To assist in evaluating the value/impact of each Bulletin  
on licensees, manpower expended in conduct of the review and  
preparation of this report is approximately one manhour. No correc-  
tive actions were necessary.

Very truly yours,

*H. G. Saddock*  
H. G. Saddock

xc: U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Washington, D. C. 20555

8009220 326

*Q*

