

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8211150193 DOC.DATE: 82/11/04 NOTARIZED: NO DOCKET #
 FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
 AUTH.NAME AUTHOR AFFILIATION
 MAIER,J.E. Rochester Gas & Electric Corp.
 RECIP.NAME RECIPIENT AFFILIATION
 CRUTCHFIELD,D. Operating Reactors Branch 5


SUBJECT: Informs that revisions to Tech Specs per 811103 request will
 be proposed following new spent fuel pool cooling sys
 installation. Proposed changes decrease time available before
 backup cooling sys required.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: ----
 TITLE: OR Submittal: General Distribution

NOTES: NRR/DL/SEP 1cy.

05000244

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	NRR ORB5 BC	01	7	7			
INTERNAL:	ELD/HDS4		1	0	NRR/DL DIR		1 1
	NRR/DL/ORAB		1	0	NRR/DSI/RAB		1 1
	<u>REG FILE</u>	04	1	1	RGN1		1 1
EXTERNAL:	ACRS	09	6	6	LPDR	03	1 1
	NRC PDR	02	1	1	NSIC	05	1 1
	NTIS		1	1			
NOTES:			1	1			



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

JOHN E. MAIER
Vice President

TELEPHONE
AREA CODE 716 546-2700

November 4, 1982

Director of Nuclear Reactor Regulation
Attention: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch No. 5
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Spent Fuel Pool Cooling System
R. E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Crutchfield:

By letter dated November 3, 1981, you approved installation of a new spent fuel pool cooling system at Ginna. Your letter requested that we propose a revision to the plant Technical Specifications to reflect the decrease in time available before backup cooling is required. Since the decreased time only can occur after the new spent fuel pool cooling system, with its higher capacity, is installed, and since we have not yet installed the new system, no change in Technical Specifications is now required. We will propose the required changes after the new system is installed. We do not expect this to occur for several years.

Very truly yours,

John E. Maier
John E. Maier

A001

8211150193	821104
PDR ADOCK 05000244	
P	PDR

THE

OF

THE

THE

THE

THE