

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y R E G 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 - 0 2 4 4 7 0 1 1 8 8 0 8 0 2 1 5 8 0 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing PT-12.1, Emergency Generator 1A, 1A Emergency Generator (EG) would
0 3 not accept nameplate steady load rating (T.S. 4.6.1.a). The 1B EG was immediately
0 4 placed in service.
0 5
0 6
0 7
0 8

0 9 SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE
CODE CODE SUBCODE CODE SUBCODE SUBCODE
E E 11 A 12 X 13 M E C F U N 14 Z 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
REPORT NUMBER 8 0 0 0 1 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
TAKEN ACTION ON PLANT METHOD 0 0 0 0 0 N SUB. SUPPLIER MANUFACTURER
E 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 A 25 W 2 9 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Adjusting governor setting to incorrect value indicated on dynotape sticker observed by
1 1 NRC inspector. Stickers should have been removed after annual overhaul by mechanics.
1 2 Setting was changed to indicated value and PT-12.1 test was performed. After test,
1 3 setting was readjusted to approximately original value and test was repeated, resulting
1 4 in achieving required load. Stickers from both EG's were removed. Required setting is
now to be logged on test procedure after yearly EG maintenance. The 1B had been
verified that it was capable of carrying required load.

1 5 FACILITY % POWER OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32
E 28 1 0 0 29 NA B 31 While performing periodic test.
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE 33 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 NA NA
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 NA
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA
7 8 9 10 11 12 80

2 0 PUBLICITY ISSUED DESCRIPTION 45
N 44 NA
7 8 9 10 11 12 80

NAME OF PREPARER S. Spector

PHONE: 716-546-2700 Ext. 291-214

8002220 365

NRC USE ONLY

