

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9007090051 DOC.DATE: 90/06/28 NOTARIZED: NO DOCKET #  
 FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244  
 AUTH.NAME AUTHOR AFFILIATION  
 MECREDY,R.C. Rochester Gas & Electric Corp.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 89-016-02 re 891117 design deficiency failure  
 of SI block/unblock switch could render some AAF inoperable.

DISTRIBUTION CODE: IE28T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+9  
 TITLE: Licensee Event Report (LER) & Part 21 Rept Combination (50 Dkt)

NOTES:License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-3 LA	1 1	PD1-3 PD	1 1
	JOHNSON,A	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	IRM TECH ADV	1 1
	NRR/ADP/DRP14E4	1 1	NRR/ADSP DIR	1 1
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB9H3	1 1
	NRR/DET/ESGB 8D	1 1	NRR/DLPQ/LHFB11	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB11	1 1
	NRR/DOEA/OGCB11	1 1	NRR/DREP/PRAB10	1 1
	NRR/DREP/PRPB11	2 2	NRR/DRIS/RSIB9A	1 1
	NRR/DRIS/RVIB9D	1 1	NRR/DST 8E2	1 0
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	NSIC SILVER,E	1 1	<u>REG FILE</u> 02	1 1
	REGION 1	1 1	REGION 2	1 1
	REGION 3	1 1	REGION 4	1 1
	REGION 5	1 1	RES/DSIR/EIB	1 1
	RES/DSR/HFB/HFS	1 1	RES/DSR/PRAB	1 1
	RGN1 FILE 01	1 1		
EXTERNAL:	EG&G STUART,V.A	4 4	INFO RECORD CTR	1 1
	L ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC MAYS,G	1 1
	NSIC MURPHY,G.A	1 1	NUDOCS FULL TXT	1 1

*Cent No*  
*8340957249*

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 52 ENCL 51

*80/14*  
*sub*

R



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001

TELEPHONE  
AREA CODE 716 546-2700

June 28, 1990

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Subject: LER 89-016 (Revision 02), Due To a Design Deficiency  
The Failure of the SI Block/Unblock Switch Could Render  
Some Automatic Actuation Features of Both Trains of SI  
Inoperable  
R.E. Ginna Nuclear Power Plant  
Docket No. 50-244

In accordance with 10 CFR 50.73, Licensee Event Report System, item (a) (2) (v) (D) and (a) (2) (vi), which requires a report of, "any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident", and in accordance with 10 CFR 21, "Reporting of Defects and Noncompliances", the attached Licensee Event Report LER 89-016 (Revision 02) is hereby submitted. This revision is necessary to add additional information obtained as a result of a review of the application of similar switches.

Due to the date of the original installation (1969), the condition is technically not 10 CFR 21 reportable. However, due to the potential significance of the failure scenario, Rochester Gas & Electric is submitting voluntary notification. Specific information regarding failure identification and corrective actions can be obtained from Mr. Richard A. Baker, Electrical Engineering, on (716) 546-2700.

This event has in no way affected the public's health and safety.

Very truly yours,

*Robert C. Mecredy*  
Robert C. Mecredy  
Division Manager  
Nuclear Production

xc: U. S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406

Ginna USNRC Senior Resident Inspector  
9007090051 900628  
PDR ADOCK 05000244  
S FDC

*Cont No*  
*P340957249*  
*IE28*  
*11*