

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9205130145 DOC.DATE: 92/05/05 NOTARIZED: NO DOCKET #  
 FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244  
 AUTH.NAME AUTHOR AFFILIATION  
 SMITH,R.E. Rochester Gas & Electric Corp.  
 RECIP.NAME RECIPIENT AFFILIATION  
 JOHNSON,A.R. Project Directorate I-3

SUBJECT: Forwards Rev 0 to "Summary Exam Rept for 1992 SG Eddy  
 Current Insp at RE Ginna Nuclear Power Station." Rept  
 summarizes observations & corrective actions resulting from  
 insps performed during 1992 refueling outage.

DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+72  
 TITLE: OR Submittal: General Distribution

NOTES:License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD1-3 LA	1 1	PD1-3 PD	1 1
JOHNSON,A	2 2		
INTERNAL: NRR/DET/ECMB 7D	1 1	NRR/DET/ESGB	1 1
NRR/DOEA/OTSB11	1 1	NRR/DST 8E2	1 1
NRR/DST/SELB 7E	1 1	NRR/DST/SICB8H7	1 1
NRR/DST/SRXB 8E	1 1	NUDOCS-ABSTRACT	1 1
OC/LEMB	1 0	OGC/HDS1	1 0
<del>REG FILE</del> 01	1 1	RES/DSIR/EIB	1 1
EXTERNAL: NRC PDR	1 1	NSIC	1 1

Cont NO  
 P748978388

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 16

R  
I  
D  
S  
/  
A  
D  
D  
S

MA-2  
117





ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001

ROBERT E. SMITH  
Senior Vice President  
Production and Engineering

May 5, 1992

TELEPHONE  
AREA CODE 716 546-2700


U.S. Nuclear Regulatory Commission  
Document Control Desk  
Attn: Allen R. Johnson  
Project Directorate I-3  
Washington, D.C. 20555

Subject: 1992 Steam Generator Eddy Current Examination  
Summary Report  
R.E. Ginna Nuclear Power Plant  
Docket No. 50-244

Dear Mr. Johnson:

In accordance with Appendix B paragraph 1.12.2.1 of the Ginna Station Quality Assurance Manual we are submitting the "Summary Examination Report for the 1992 Steam Generator Eddy Current Inspection at R.E. Ginna Nuclear Power Station." This report summarizes observations and corrective actions resulting from inspections performed during the 1992 refueling outage, identifies the location and extent of each indication, and the tubes which have been plugged or sleeved in each steam generator.

Very truly yours,

  
Robert E. Smith

GJW\101

xc: Mr. Allen R. Johnson (Mail Stop 14D1)  
Project Directorate I-3  
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406

Ginna Senior Resident Inspector

*Ent No 9748978388*  
*Acc 11*

9205130145	920505
PDR ADDCK	05000244
Q	PDR

