

B001  
PAGE 1

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-397 WPPS-2  
RECIPIENT: VARGA, S.A.  
ORIGINATOR: RENNBERGER, D.L.  
COMPANY NAME: WA PUB PWR SUPPLY SYS  
SUBJECT:

DOC DATE: 781024  
ACCESSION NBR: 7811010119  
COPIES RECEIVED:  
LTR 1 ENCL 0  
SIZE: 2

Corrects Addenda 1 to Air Products & Chem, Inc rept #APCI-78-6p submitted 780918. W/encl Errata sheet.

NOTARIZED

DISTRIBUTION CODE: B001

DISTRIBUTION TITLE:

PSAR/FSAR AMDTS AND RELATED CORRESPONDENCE

NAME	ENCL?	FOR ACTION
ASST DIR	LTR ONLY	• <u>VASSALLO</u>
BR CHIEF	LTR ONLY	• <u>LWR#4 BC</u>
PROJ MGR	W/ENCL	• <u>M LYNCH</u>
LIC ASST	LTR ONLY	• <u>LWR#4 LA</u>
REG FILE	W/ENCL	
NRC PDR	W/ENCL	
I & E	W/2 ENCL	
OELD	LTR ONLY	
OPERATOR LIC BR	W/ENCL	
EMERGENCY PLAN BR	W/ENCL	
OAB	W/ENCL	
DIRECTOR NRR	LTR ONLY	
MIPC	LTR ONLY	
AD FOR ENG	LTR ONLY	
MECH ENG BR	W/ENCL	
STRUCTURAL ENG BR	W/ENCL	
MATERIAL ENG BR	W/2 ENCL	
AD FOR REAC SFTY	LTR ONLY	

NOTES:

NOV 3 1978

MA 4  
60

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: \_\_\_\_\_  
RECIPIENT: \_\_\_\_\_  
ORIGINATOR: \_\_\_\_\_

DOC DATE: \_\_\_\_\_  
ACCESSION NBR: \_\_\_\_\_  
COPIES RECEIVED: \_\_\_\_\_  
LTR \_\_\_\_\_ ENCL \_\_\_\_\_  
SIZE: \_\_\_\_\_

SUBJECT: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

FOR ACTION

REACTOR SYSTEMS BR	W/ENCL
ANALYSIS BR	W/ENCL
CORE PERFORMANCE BR	W/ENCL
AD FOR PLANT SYSTEMS	LTR ONLY
AUXILIARY SYS BR	W/ENCL
CONTAINMENT SYSTEMS	W/ENCL
I & C SYSTEMS BR	W/ENCL
POWER SYS BR	W/ENCL
AD FOR SITE TECH	W/5 ENCL
AD FOR SITE ANALYS	LTR ONLY
ACCIDENT ANALYSIS	W/ENCL
EFFLUENT TREAT SYS	W/ENCL
RAD ASSESSMENT BR	W/ENCL
KIRKWOOD	W/ENCL
GEOSCIENCES BR	W/ENCL
LPDR	W/ENCL
TERA	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL


\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TOTAL NUMBER OF COPIES REQUIRED:

LTR  
ENCL

58  
48

NOTES:



Washington Public Power Supply System  
A JOINT OPERATING AGENCY

P. O. Box 968

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

G02-78-241  
October 24, 1978

Docket No. 50-397

Mr. S. A. Varga, Chief  
Light Water Reactor Branch No. 4  
Division of Project Management  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

REGULATORY DOCKET FILE COPY

Subject: WPPSS NUCLEAR PROJECT NO. 2  
POST-LOCA HYDROGEN RECOMBINER  
SUPPLEMENTAL INFORMATION  
ADDENDA CORRECTIONS

Reference: Letter, G02-78-223, DL Renberger to SA Varga,  
same subject, dated September 18, 1978

Dear Mr. Varga:

The reference transmitted to you Addenda 1 to the Air Products and Chemical, Inc. report APCI-78-6P. Subsequent to that submittal four (4) items have been identified which require correction. These items are listed on the attached errata sheet.

We apologize for any inconvenience this may cause you. If you require further clarification, please contact Mr. O. K. Earle of Project Licensing.

Very truly yours,

*D L Renberger*

D. L. RENBERGER  
Assistant Director  
Technology

DLR:DCT:cph

attachment: as stated

cc: JJ Verderber, B&R  
JJ Byrnes, B&R  
HR Canter, B&R  
RC Root, B&R Site  
NS Reynolds, DeBevoise & Liberman  
D. Roe, BPA

REGULATORY DOCKET FILE COPY

781101.0119

3001  
5/10



Errata Sheet To Addenda 1 To APCI-78-6P

<u>Page</u>	<u>Comment</u>
Cover Sheet	Proprietary statement should reference APCI-78-6P, not APCI-78-7P.
1	Response to item 1 should refer to FSAR paragraph 6.2.1.1.8, not 5.2.1.1.8.
6	In item 10 reference to the scrubber water flow control valve should be CAC-FCV-5A, not CAV-FCV-5A.
8	Item 13 refers to pressure gauge PI-2A. The range is 0-30 psig, not 0-20 psig.