

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7901250152 DOC. DATE: 79/01/17 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project-1, Washington Public Power Supp 05000397
 AUTH. NAME AUTHOR AFFILIATION
 RENBERGER, D.L. Washington Public Power Supply System
 RECIP. NAME RECIPIENT AFFILIATION
 ENGELKEN, R.G. Region 5, San Francisco, Office of the Director

SUBJECT: Forwards Deficiency Rept re routing of Class IE cable trays
 in seismic 2 area.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: Bill Paton OELD 1 cy ER AMDTs.

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM H LYNCH	1 1	15 BC LWR#4	1 1
	20 LA LWR#4	1 1	21 AD VASSALLO	1 1
INTERNAL:	01 REG FILE	1 1	02 NRC PDR	1 1
	05 I&E	2 2	07 EDO & STAFF	1 1
	08 MPA	1 1	09 DEPY DIR DPM	1 1
	10 QAB	1 1	11 STANDRDS DEV	1 1
	12 JORDAN, E/IE	1 1	13 FIELD COOR/IE	1 1
	16 AD FOR ENGR	1 1	17 AD PLANT SYS	1 1
	17 AD REAC SFTY	1 1	19 AD SYS/PROJ	1 1
	22 DIR DPM	1 1	23 OELD	1 1
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

JAN 26 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39


MA 1
GD

THE UNITED STATES OF AMERICA
DO hereby certify that

the within and foregoing is a true and correct copy of the original as the same appears on the records of the

Department of the Interior, Bureau of Land Management, at Washington, D. C.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 988

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

G02-79-17
January 17, 1979

Nuclear Regulatory Commission
Region V
Suite 202 Walnut Creek Plaza
1900 N. California Boulevard
Walnut Creek, California 94596

ATTN: Mr. R. H. Engelken, Director

SUBJECT: WPPSS NUCLEAR PROJECT NO. 2
DOCKET #50-397, CPPR-93
REPORTABLE DEFICIENCY - 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR 50.55(e), your staff was informed by telephone on December 18, 1978, of a reportable deficiency involving routing of Class IE cable trays in a seismic II area.

Attached is our report on this deficiency.

Please contact us if you have additional questions.

Very truly yours,

D L Renberger

D. L. RENBERGER
Assistant Director
Technology

DLR:RLB:cph

attachment

cc: JJ Verderber - B&R, w/att

JJ Byrnes - B&R, "

D. Roe, BPA, "

~~For the General Director, NRC, w/att~~

WNP-2 Files, w/att

REGULATORY DOCKET FILE COPY

7901250152

*Boig
5/11*

5