

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:7903210093 DOC.DATE: 79/03/13 NOTARIZED: NO DOCKET: #  
 FACIL:50-397 WPPSS NUCLEAR PROJECT, UNIT 2, WASHINGTON PUBLIC POWER 05000397  
 AUTH.NAME AUTHOR AFFILIATION  
 RENBERGER,D.L. WASHINGTON PUBLIC POWER SUPPLY SYSTEM  
 RECIP.NAME RECIPIENT AFFILIATION  
 ENGELKEN,R.H. REGION 5, SAN FRANCISCO, OFFICE OF THE DIRECTOR

SUBJECT: FORWARDS REPT RE DEFECTIVE WELDS IN PIPE WHIP RESTRAINT  
 BRACKETS INSIDE CONTAINMENT.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1/1  
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: BILL PATON OELD NUCY ER AMDT'S

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM M LYNCH	1 1	15 BC LWR #4	1 1
	20 LA LWR #4	1 1	21 AD VASSALLO	1 1
INTERNAL:	01 REG FILE	1 1	02 NRC PDR	1 1
	05 I&E	2 2	07 EDO & STAFF	1 1
	08 MPA	1 1	09 DEPY DIR DPM	1 1
	10 QAB	1 1	11 STANDRDS DEV	1 1
	12 JORDAN, E/IE	1 1	13 FIELD COOR/IE	1 1
	16 AD FOR ENGR	1 1	17 AD PLANT SYS	1 1
	17 AD REAC SFTY	1 1	19 AD SYS/PROJ	1 1
	22 DIR DPM	1 1	23 OELD	1 1
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

MAR 23 1979


MA 1  
60

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39

1. The first part of the document is a list of names and addresses. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into columns, with names in the first column and addresses in the second column.

2. The second part of the document is a list of names and addresses, similar to the first part. The names are written in a cursive script, and the addresses are written in a more formal, printed style. The list is organized into columns, with names in the first column and addresses in the second column.

Name	Address	City	State
J. H. Smith	123 Main St	New York	NY
W. J. Brown	456 Oak St	Chicago	IL
M. L. Green	789 Pine St	Boston	MA
R. K. White	101 Elm St	Philadelphia	PA
S. P. Black	234 Maple St	San Francisco	CA
T. Q. Red	567 Cedar St	Los Angeles	CA
V. R. Blue	890 Birch St	Houston	TX
Y. S. Yellow	1123 Spruce St	Portland	OR
Z. T. Purple	1456 Ash St	Seattle	WA



Washington Public Power Supply System  
A JOINT OPERATING AGENCY

P. O. Box 988

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

March 13, 1979  
G02-79-40

Nuclear Regulatory Commission  
Region V  
Suite 202 Walnut Creek Plaza  
1900 N. California Boulevard  
Walnut Creek, California 94596

ATTN: Mr. R. H. Engelken, Director

SUBJECT: WPPSS NUCLEAR PROJECT NO. 2  
DOCKET #50-397, CPPR-93  
REPORTABLE DEFICIENCY - 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on February 9, 1979, of a reportable deficiency involving defective welds in the pipe whip restraint brackets inside containment.

Attached is our report on this deficiency.

Please contact us if you have additional questions.

Very truly yours,

D. L. RENBERGER  
Assistant Director  
Technology

DLR:MBP:cph

attachment

cc: JJ Verderber - B&R, w/att  
JJ Byrnes - B&R, w/att  
D. Roe, BPA, w/att  
E. Volgenau, Director, NRC, w/att  
WNP-2 Files, w/att

RECEIVED  
WASHINGTON PUBLIC POWER SUPPLY SYSTEM  
MAR 15 1979  
CPPV

7903210093

5019  
5.11