

Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968


3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 373-3000

November 30, 1979
G02-79-212

Nuclear Regulatory Commission
Region V
Office of Inspection and Enforcement
Suite 202, Walnut Creek Plaza
1900 North California Boulevard
Walnut Creek, CA 94596



Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397
REPORTABLE DEFICIENCY - 10CFR50.55(e)

References: Letter G02-79-191 from D. L. Renberger to R. H. Engelken
dated October 18, 1979, same subject

Dear Mr. Engelken:

The referenced letter documented a reportable condition in accordance with the provisions of 10CFR50.55(e) involving the WNP-2 spent fuel pool cooling system. The letter also included an interim report of the deficiency.

The final report of action being taken to correct this condition is attached.

Please contact us if you have additional questions.

Very truly yours,

D. L. RENBERGER

Assistant Director Technology

DLR:TRM:cd

attachment: as stated

cc: JM Blas - B&R w/att
JJ Verderber - B&R w/att
RE Snaith - B&R w/att
JR Lewis - BPA w/att
JG Davis, Director, NRC, Washington, D.C., w/att
RC Root - B&R Site w/att
MJ Parise - B&R Site w/att
WNP-2 files w/att
GT Harper - B&R Site w/att

7912280 642

77-139

2. 10
11 12 13