

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

MA/2

ACCESSION NBR:8004020302 DOC.DATE: 80/03/21 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH.NAME AUTHOR AFFILIATION
 RENBERGER,D.L. Washington Public Power Supply System
 RECIP.NAME RECIPIENT AFFILIATION
 ENGELKEN,R.H. Region 5, San Francisco, Office of the Director

SUBJECT: Forwards final deficiency rept re pipe whip restraint problems.


DISTRIBUTION CODE: 8019S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: PM - 2 CYS ALL MATL.

| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
| ACTION: | 14 PM <i>M. LYNCH</i> | 1 1 | 15 BC <i>LWR #4</i> | 1 1 |
| | 20 LA <i>LWR #4</i> | 1 1 | 21 AD <i>LWR</i> | 1 1 |
| INTERNAL: | <u>01 REG FILE</u> | 1 1 | 02 NRC PDR | 1 1 |
| | 05 I&E | 2 2 | 07 EDO & STAFF | 1 1 |
| | 08 MPA | 1 1 | 09 DEPY DIR DPM | 1 1 |
| | 10 QAB | 1 1 | 11 STANDRDS DEV | 1 1 |
| | 13 FIELD COOR/IE | 1 1 | 16 AD FOR ENGR | 1 1 |
| | 17 AD PLANT SYS | 1 1 | 17 AD REAC SFTY | 1 1 |
| | 22 DIR DPM | 1 1 | 23 OELD | 1 1 |
| | AD/RCI/IE | 1 1 | AD/SITE TECH | 1 1 |
| | AEOD | 1 1 | DIRECTOR DSE | 1 1 |
| | GEOSCIENCES BR | 1 1 | HANAUER, S. | 1 1 |
| | I&C SYS BR | 1 1 | MATL ENG BR | 1 1 |
| | MECH ENG BR | 1 1 | POWER SYS BR | 1 1 |
| | STRUCT ENG BR | 1 1 | | |
| | EXTERNAL: | 03 LPDR | 1 1 | 04 NSIC |
| | 24 ACRS | 16 16 | | |




APR 3 1980



TOTAL NUMBER OF COPIES REQUIRED: LTR 50 ENCL 50
~~48~~ ~~48~~

rtj



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. BOX 988

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

March 21, 1980
G02-80-74

Mr. R. H. Engelken, Director
Nuclear Regulatory Commission
Region V
Office of Inspection and Enforcement
Suite 202, Walnut Creek Plaza
1990 N. California Boulevard
Walnut Creek, California 94596

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397, CPPR-93
CORRECTIVE ACTION PROGRAM FOR RESOLUTION
OF PIPE WHIP RESTRAINT PROBLEMS,
REPORTABLE DEFICIENCY 10CFR50.55(e)

- Reference: 1) Letter G02-79-226, DL Renberger to RH Engelken,
dated 12/10/79
- 2) Letter G02-80-28, DL Renberger to RH Engelken,
dated 2/1/80
- 3) NRC Letter, RH Engelken to NO Strand,
dated 2/8/80

Dear Mr. Engelken:

Reference 1) responded to NRC concerns associated with the Pipe Whip Restraint Corrective Action Program and was established as an interim 50.55(e) report in a telephone conversation with D. Haist of Region V.

Reference 2) letter provided more detailed information on the Pipe Whip Restraint Corrective Action Program. Reference 3) concurred with our plans for corrective action.

This letter constitutes our final report under the provisions of

Boia
3/11

8004020 302

50.55(e) on the corrective action for the Pipe Whip Restraints.
The status is attached.

Please contact us if you have any questions.

Very truly yours,



D. L. RENBERGER
Assistant Director
Technology

DLR/JEL/ln

Attachment: As stated

cc: JM Blas - B&R, NY
HR Canter - B&R, NY
Spike Ford, NUS
JR Lewis - BPA, Richland
V Stello - Office of Inspection & Enforcement,
Washington, D.C.
JJ Verderber - B&R, NY