

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8203170331 DOC. DATE: 82/03/02 NOTARIZED: NO DOCKET #  
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397  
 AUTH. NAME AUTHOR AFFILIATION  
 BOUCHEY, G.D. Washington Public Power Supply System  
 RECIP. NAME RECIPIENT AFFILIATION  
 SCHWENCER, A. Licensing Branch 2

SUBJECT: Responds "Licensing Qualification Branch SER open items per  
 820226 request. Shift support supervisor will receive  
 training as identified in Section 13.2.1.1.2," Initial  
 Non-License Operator Training Program.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: PSAR/FSAR AMDTS and Related Correspondence

NOTES: 2 copies all matl: PM.

05000397

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
A/D LICENSNG		1	0	LIC BR #2 BC		1	0
LIC BR #2 LA		1	0	AULUCK, R.	01	1	0
INTERNAL: ELD		1	0	IE	06	1	0
IE/DEP/EPDB	35	1	1	IE/DEP/EPLB	36	3	5
MPA		1	0	NRR/DE/CEB	11	1	1
NRR/DE/eqB	13	3	5	NRR/DE/GB	28	2	2
NRR/DE/HGEB	30	2	2	NRR/DE/MEB	18	1	1
NRR/DE/MTEB	17	1	1	NRR/DE/QAB	21	1	1
NRR/DE/SAB	24	1	1	NRR/DE/SEB	25	1	1
NRR/DHFS/HFEB	40	1	1	NRR/DHFS/LQB	32	1	1
NRR/DHFS/OLB	34	1	1	NRR/DHFS/PTRB	20	1	1
NRR/DSI/AEB	26	1	1	NRR/DSI/ASB	27	1	1
NRR/DSI/CPB	10	1	1	NRR/DSI/CSB	09	1	1
NRR/DSI/ETSB	12	1	1	NRR/DSI/ICSB	16	1	1
NRR/DSI/PSB	19	1	1	NRR/DSI/RAB	22	1	1
NRR/DSI/RSB	23	1	1	NRR/DST/LGB	33	1	1
<u>REG FILE</u>	04	1	1	RGNS		1	1
EXTERNAL: ACRS	41	16	16	BNL (AMDTS ONLY)		1	1
FEMA-REP DIV	39	1	1	LPDR	03	1	1
NRC PDR	02	1	1	NSIC	05	1	1
NTIS		1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 64 ENCL 51




## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

March 2, 1982  
G02-82-279  
SS-L-02-RMN-82-005

Docket No. 50-397

Mr. A. Schwencer, Chief  
Licensing Branch No. 2  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555



Dear Mr. Schwencer:

Subject: NUCLEAR PROJECT NO. 2  
SER OPEN ITEMS  
LICENSING QUALIFICATION BRANCH

As requested during a phone conversation between Messrs. R. Auluck and F. Allenspach of your staff and Messrs. R.M. Nelson and R.D. Davidson of the Supply System on February 26, 1982, the following information was provided:

Problem 1: The Training Program for Shift Support Supervisor is not described in Section 13.2.

Response: The Shift Support Supervisor will, as a minimum, receive the training as identified in Section 13.2.1.1.2, i.e., Initial Non-License Operator Training Program. In addition, the Shift Support Supervisor will attend applicable General Employee Training as identified in Section 13.2.1.1.7 and Fire Brigade Training as identified in Section 13.2.1.1.8.1.

Problem 2: Individuals required to receive training in mitigation of core damage are not listed in II.B.4, Appendix B.


Boo1  
s  
1/0



Mr. A. Schwencer  
Page Two  
March 2, 1982  
G02-82-279

Response: The WNP-2 position, is stated in the updated response to Section II.B.4 of Appendix B (submittal G02-82-27, dated January 11, 1982), "Training for Mitigating Core Damage". As a clarification to this position, plant personnel who may provide management support in the event of an emergency will attend applicable sections of the Mitigating Core Damage Training Program.

Very truly yours,



G. D. Bouchey  
Deputy Director, Safety and Security

RMN/jca

cc: R Auluck - NRC  
WS Chin - BPA  
R Feil - NRC Site  
R Allenspach - NRC

