

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8306280453 DOC. DATE: 83/06/21 NOTARIZED: NO DOCKET #  
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397  
 AUTH. NAME AUTHOR AFFILIATION  
 BOUCHEY, G. D. Washington Public Power Supply System  
 RECIP. NAME RECIPIENT AFFILIATION  
 SCHWENCER, A. Licensing Branch 2

SUBJECT: Forwards "Control Sys Failures Evaluation Rept,"  
 inadvertently omitted from 830610 response to NRC request  
 for info re SER 3 Outstanding Issue 13.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+26  
 TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
NRR/DL/ADL		1	0	NRR LB2 BC		1	0
NRR LB2 LA		1	0	AULUCK, R.	01	1	1
INTERNAL: ELD/HDS2		1	0	IE FILE		1	1
IE/DEPER/EPB	36	3	3	IE/DEPER/IRB	35	1	1
IE/DEQA/QAB	21	1	1	NRR/DE/AEAB		1	0
NRR/DE/CEB	11	1	1	NRR/DE/EHEB		1	1
NRR/DE/eqB	13	2	2	NRR/DE/GB	28	2	2
NRR/DE/MEB	18	1	1	NRR/DE/MTEB	17	1	1
NRR/DE/SAB	24	1	1	NRR/DE/SGEB	25	1	1
NRR/DHFS/HFEB	40	1	1	NRR/DHFS/LQB	32	1	1
NRR/DHFS/PSRB		1	1	NRR/DL/SSPB		1	0
NRR/DSI/AEB	26	1	1	NRR/DSI/ASB		1	1
NRR/DSI/CPB	10	1	1	NRR/DSI/CSB	09	1	1
NRR/DSI/ICSB	16	1	1	NRR/DSI/METB	12	1	1
NRR/DSI/PSB	19	1	1	NRR/DSI/RAB	22	1	1
NRR/DSI/RSB	23	1	1	REG FILE	04	1	1
RGNS		3	3	RM/DDAMI/MIB		1	0
EXTERNAL: ACRS	41	6	6	BNL (AMDTS ONLY)		1	1
DMB/DSS (AMDTS)		1	1	FEMA-REP DIV	39	1	1
LPDR	03	1	1	NRC PDR	02	1	1
NSIC	05	1	1	NTIS		1	1



## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

June 21, 1983  
G02-83-541  
NS-L-02-JCA-83-055

Docket 50-397

Director of Nuclear Reactor Regulation  
Attention: Mr. A. Schwencer, Chief  
Licensing Branch No. 2  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555


Dear Mr. Schwencer:

Subject: NUCLEAR PROJECT NO. 2  
CONTROL SYSTEM FAILURES QUESTIONS,  
WNP-2 SER #3, OUTSTANDING ISSUE #13,  
ADDITIONAL SUBMITTAL

Reference: Letter, G02-83-509, G. D. Bouchey (SS) to  
A. Schwencer (NRC), Same Subject, dated  
June 10, 1983

Per the referenced letter, the "Control System Failures" questions (031.135, 031.137, and 031.138) were submitted to the NRC for review and concurrence. A section of NRC Question 031.138, "Control System Failures", was inadvertently left out; enclosed is the additional information for your review (5 copies).

Very truly yours,



G. D. Bouchey  
Manager, Nuclear Safety and Regulatory Programs

JCA/tmh  
Enclosure

cc: R Auluck - NRC  
WS Chin - BPA  
A Toth - NRC Site

8306280453 830621  
PDR AD0CK 05000397  
E PDR

B001  
1/1

