

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8411200173 DOC. DATE: 84/11/14 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME: SORENSEN, G.C. AUTHOR AFFILIATION: Washington Public Power Supply System
 RECIP. NAME: SCHWENCER, A. RECIPIENT AFFILIATION: Licensing Branch 2

SUBJECT: Discusses util approach to updating FSAR, per 10CFR50.71(e).
 Replacement pages will be provided in Dec 1985 to reflect
 as-built plant up to June 1985. Complete FSAR rewrite not
 necessary for recently licensed plants.

DISTRIBUTION CODE: A053D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: Updated FSAR (50.71)

NOTES: OL: 12/20/83 05000397

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	AULUCK, R	01	1				
INTERNAL:	ACRS	09	2		IE FILE	05	1
	NRR ROE, M.L		1		REG FILE	02	1
	RGNS	06	2				
EXTERNAL:	DMB/DSS		1		FRANKLIN		1
	LPDR	04	1		NRC PDR	03	1
	NSIC		1		NTIS		1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 14

THE UNITED STATES OF AMERICA
 DEPARTMENT OF THE ARMY
 OFFICE OF THE CHIEF OF STAFF
 WASHINGTON, D. C. 20315
 10 JAN 68

SUBJECT: [Illegible]
 REFERENCE: [Illegible]
 ACTION: [Illegible]

1. [Illegible]
 2. [Illegible]
 3. [Illegible]

ACTION	DATE	BY	REMARKS
1	20	JH	[Illegible]
2	20	JH	[Illegible]
3	20	JH	[Illegible]
4	20	JH	[Illegible]
5	20	JH	[Illegible]

Washington Public Power Supply System

3000 George Washington Way P.O. Box 968 Richland, Washington 99352-0968 (509)372-5000

Docket No. 50-397

November 14, 1984
G02-84-582

Director, Office of Nuclear Reactor Regulation
Attention: Mr. A. Schwencer, Chief
Licensing Branch No. 2
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Schwencer:

Subject: SUPPLY SYSTEM NUCLEAR PLANT NO. 2
OPERATING LICENSE NO. NPF-21
REQUIREMENT TO UPDATE FSAR - 10CFR50.71(e)

The Code of Federal Regulations, 10CFR50.71(e) requires the submittal of an updated Final Safety Analysis Report within 24 months after issuance of an Operating License. As we have discussed, it is the Supply System's understanding that this update need not be a complete rewrite of the FSAR, but must contain "all the changes necessary to reflect information and analyses submitted to the Commission ... since ... the last updated FSAR" (10CFR50.71(e)).

As the WNP-2 FSAR has been continuously updated since the initial submittal as part of our Operating License review, it is our intent to provide replacement pages in December 1985 necessary to reflect the "as-built" plant up to June 1985.

We recognize that other updated FSAR's received by the staff since this rule became effective have been complete rewrites. For the older plants, this was obviously a necessity. However, for recently licensed plants, this was, to the best of our knowledge a choice made by the utility. We are not aware of specific direction from the staff requiring a complete rewrite.


8411200173 841114
PDR ADDCK 05000397
P PDR

A053
1/0

Mr. A. Schwencer
Page Two

The purpose of this letter, therefore, is to advise you of the approach we are taking to update the FSAR. Should your understanding of the regulation be different than ours or if you are aware of specific staff guidance that would not permit what we have proposed, please let me know as soon as possible.

Very truly yours,

A handwritten signature in cursive script, appearing to read "G. C. Sorensen".

G. C. Sorensen, Manager
Regulatory Programs

GCS/kd

cc: R. Auluck - NRC
N.S. Reynolds, Bishop, Liberman, Cook, Purcell & Reynolds
A. Toth - NRC (901A)

