

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8504010159 DOC. DATE: 85/03/26 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Power -05000397
 AUTH. NAME: SORENSEN, G.C. AUTHOR AFFILIATION: Washington Public Power Supply System
 RECIP. NAME: SCHWENCER, A. RECIPIENT AFFILIATION: Licensing Branch 2

SUBJECT: Submits clarification to 850205 response to Generic Ltr
 84-24, Paragraph b concerning justification for interim
 operation of equipment environ qualification program.

DISTRIBUTION CODE: A048D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR/Licensing Submittal: Equipment Qualification

NOTES:

OL: 12/20/83

05000397

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL.		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL.
	NRR LB2 BC	12	1		AULUCK, R	01	1
INTERNAL:	ACRS	15	8		ADM/LFMB		1
	ELD/HDS2	12	1		ELD SHIELDS, W		1
	GC	13	1		NRR KARSCH, R		1
	NRR/DE/EQB	07	2		NRR/DL DIR	14	1
	NRR/DSI/AEB		1		REG FILE	04	1
	RGN5		1				
EXTERNAL:	LPDR	03	1		NRC PDR	02	1
	NSIC	05	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 2

...the ...
...the ...
...the ...

1. The first of these is the fact that the Government has not been able to secure the necessary funds to carry out its policy. This is due to the fact that the Government has not been able to secure the necessary funds to carry out its policy.

[illegible]

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000
March 26, 1985
G02-85-169

Docket No. 50-397

Director of Nuclear Reactor Regulation
Attention: Mr. A. Schwencer, Chief
Licensing Branch No. 2
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Schwencer:

Subject: NUCLEAR PLANT NO. 2
EQUIPMENT ENVIRONMENTAL QUALIFICATION PROGRAM,
RESPONSE TO GENERIC LETTER 84-24, CLARIFICATION


Reference: Letter, G02-85-052, G. C. Sorensen (SS) to A.
Schwencer (NRC), Same Subject, dated February 5,
1985

As a result of a February 15, 1985 telephone conversation with the NRC Staff, it was requested that the Supply System provide further clarification regarding paragraph b) of the reference letter. The following rewording of that paragraph is proposed to supersede that in the reference letter to reduce the possibility of misunderstandings:

"b) in compliance with 10CFR50.49, the Supply System prepared a Justification for Interim Operation. This document was deemed acceptable by the NRC Staff prior to issuance of the Operating License. WNP-2 is operating with one path to safe shutdown either fully qualified or justified for interim operation by appropriate documentation on file with the NRC."

Please include this clarification in our response to Generic Letter 84-24. Should you have any questions, please contact Mr. P. L. Powell, Manager, WNP-2 Licensing.

Very truly yours,


G. C. Sorensen, Manager
Regulatory Programs

KRW/tmh

cc: R Auluck - NRC
JO Bradfute - NRC
WS Chin - BPA
JB Martin - NRC RV
E Revell - BPA
AD Toth - NRC Site

8504010159 850326
PDR ADUCK 05000397
PDR

A048
1/0

100-100000