

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8506040176 DOC. DATE: 85/05/28 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME: SORENSEN, G.C. AUTHOR AFFILIATION: Washington Public Power Supply System
 RECIP. NAME: BUTLER, W.R. RECIPIENT AFFILIATION: Licensing Branch 2

SUBJECT: Informs that encl to NRC 850506 request for addl info re
 Generic Ltr 83-28 inadvertently removed prior to mailing &
 not received until 850520. Scheduled 45-day response interval
 will use 850520 as start date.

DISTRIBUTION CODE: A055D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR/Licensing Submittal: Salem ATWS Events GL-83-28

NOTES:

05000397

OL: 12/20/83

RECIPIENT			COPIES		RECIPIENT			COPIES	
ID	CODE/NAME		LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL	
NRR	LB2 BC	01	3	3					
INTERNAL:	ACRS		6	6	ADM/LFMB		1	1	
	ELD/HDS2		1	0	IE/DI		1	1	
	IE/DQAVT		1	1	NRR/DE/EQB		1	1	
	NRR/DE/MEB		1	1	NRR/DHFS/HFEB		1	1	
	NRR/DHFS/LQB		1	1	NRR/DL DIR		1	1	
	NRR/DL/ORAB		1	1	NRR/DL/SSPB		1	1	
	NRR/DL/TAPMG		1	1	NRR/DSI/ASB		1	1	
	NRR/DSI/ICSB		2	2	NRR/DSI/PSB		1	1	
	NRR/DSI/RSB		1	1	REG FILE	04	1	1	
	RGNS		1	1					
EXTERNAL:	24X		1	1	LPDR	03	1	1	
	NRC PDR	02	1	1	NSIC	05	1	1	

TOTAL NUMBER OF COPIES REQUIRED: LTTR 32 ENCL 30

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that this is crucial for the company's financial health and for providing reliable information to stakeholders.

2. The second part of the document outlines the specific procedures for recording transactions. It details the steps from initial entry to final review, ensuring that all necessary information is captured and verified.

3. The third part of the document addresses the role of the accounting department in this process. It highlights the need for clear communication and collaboration between different teams to ensure the accuracy and timeliness of the records.

4. The fourth part of the document provides a summary of the key points discussed. It reiterates the importance of accurate record-keeping and the need for consistent adherence to the established procedures.

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

8506040176 850528
PDR ADDCK 05000397
P PDR

May 28, 1985
G02-85-269

Docket No. 50-397

Director of Nuclear Reactor Regulation
Attention: Mr. W. R. Butler, Chief
Licensing Branch No. 2
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Butler:


Subject: NUCLEAR PLANT NO. 2
RESPONSE TO REQUEST FOR ADDITIONAL
INFORMATION ON GENERIC LETTER 83-28

Reference: Letter, A. Schwencer (NRC) to G. C. Sorensen (SS),
Same Subject, dated May 6, 1985

The reference letter requested additional information, described in an enclosure, and requested a response within 45 days of receipt of the letter. The enclosure was inadvertently removed prior to mailing. As a result, it was not received until May 20, 1985. For purposes of responding, the Supply System will use May 20, 1985 for the scheduled 45 day response interval.

Should you have any questions, please contact Mr. P. L. Powell, Manager, WNP-2 Licensing.


Very truly yours,



G. C. Sorensen, Manager
Regulatory Programs

PLP/tmh

cc: JO Bradfute - NRC
WS Chin - BPA
JB Martin - NRC RV
E Revell - BPA
AD Toth - NRC Site



A055
1/0

