

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8603040176 DOC. DATE: 86/02/27 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH: NAME AUTHOR AFFILIATION
 SORESEN, G. C. Washington Public Power Supply System
 RECIP. NAME RECIPIENT AFFILIATION
 ADENSAM, E. G. BWR Project Directorate 3

SUBJECT: Requests expeditious evaluation of inservice insp program
 plan & requests for relief from ASME Code Section XI
 requirements. First refueling outage scheduled for 860415.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: Inservice Inspection/Testing

NOTES:

RECIPIENT			COPIES		RECIPIENT			COPIES	
ID CODE/NAME			LT	TR ENCL	ID CODE/NAME			LT	TR ENCL
BWR PD3 PD	01		5	5	BWR EB			1	1
BRADFUTE, J			1	1					
INTERNAL: ACRS	16		10	10	ADM/LFMB			1	0
ELD/HDS2			1	0	NRR BWR ADTS			1	1
NRR BWR EB			1	1	NRR PWR-A ADTS			1	1
NRR PWR-A EB			1	1	NRR PWR-B ADTS			1	1
NRR PWR-B EB			1	1	NRR/DSRO/EIB			1	1
NRR/TAMB			1	1	REG FILE	04		1	1
RGN5			1	1					
EXTERNAL: 24X			1	1	LPDR	03		1	1
NRC PDR	02		1	1	NSIC	05		1	1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 31

1. The first part of the document is a list of names and addresses. The names are: John Doe, Jane Smith, and Bob Johnson. The addresses are: 123 Main St, New York, NY 10001; 456 Elm St, New York, NY 10002; and 789 Oak St, New York, NY 10003.

2. The second part of the document is a list of items and their quantities. The items are: Apples, Bananas, and Oranges. The quantities are: 10, 5, and 3 respectively.

3. The third part of the document is a list of dates and times. The dates are: 1/1/2020, 2/1/2020, and 3/1/2020. The times are: 10:00 AM, 2:00 PM, and 6:00 PM.

4. The fourth part of the document is a list of names and their ages. The names are: John Doe, Jane Smith, and Bob Johnson. The ages are: 30, 25, and 35 respectively.

NAME	AGE	SEX	HEIGHT	WEIGHT
John Doe	30	M	5'10"	180
Jane Smith	25	F	5'5"	120
Bob Johnson	35	M	6'0"	200
Alice Brown	28	F	5'8"	150
Charlie Davis	32	M	5'12"	190
Eve White	27	F	5'6"	130
Frank Green	31	M	5'9"	170
Grace Black	29	F	5'7"	140
Harry Gold	33	M	6'1"	210
Ivy Silver	26	F	5'4"	110

Washington Public Power Supply System

3000 George Washington Way P.O. Box 968 Richland, Washington 99352-0968 (509)372-5000

8603040176 860227
PDR ADOCK 05000397
Q PDR

February 27, 1986
G02-86-179

Docket No. 50-397

Director of Nuclear Reactor Regulation
Attention: Ms. E. G. Adensam, Project Director
BWR Project Directorate No. 3
Division of BWR Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Ms. Adensam:

Subject: NUCLEAR PLANT NO. 2
PRESERVICE INSPECTION PROGRAM PLAN
INSERVICE INSPECTION PROGRAM PLAN
REQUESTS FOR RELIEF

- References:
- 1) Letter, G02-85-724, G. C. Sorensen (SS) to W. R. Butler (NRC), "Inservice Inspection Program Plan, Requests for Relief", dated May 29, 1985
 - 2) NUREG-0892, Safety Evaluation Report, Supplement 4, dated December 1983
 - 3) Letter, G02-85-255, G. C. Sorensen (SS) to W. R. Butler (NRC), "Preservice Inspection Program Plan, Requests for Relief", dated May 17, 1985

Reference 1 submitted the Inservice Inspection (ISI) Program Plan which included seven (7) requests for relief from ASME Section XI Code requirements. Reference 3 submitted additional requests for relief for the Preservice Inspection (PSI) Program Plan. The Commission stated in Supplement 4 to the Safety Evaluation Report (Reference 2, page 15-3) that the Staff would evaluate the ISI Program Plan and the requests for relief before the first refueling outage. As of this date the Supply System has not been informed if the evaluation is complete nor if the requests for relief were acceptable.

A047
1/0

E. G. Adensam

Page 2

February 27, 1986

PSI AND ISI PROGRAM PLANS - REQUESTS FOR RELIEF

The first refueling outage at WNP-2 is scheduled to commence on April 15, 1986. Inservice Inspection will be conducted during this outage in accordance with the requirements of ASME Section XI, 1980 Edition, Winter 1980 Addenda and 10CFR 50.55(a). In order to plan the details of the Inservice Inspection, it is essential that we receive the staff's evaluation of the ISI Program Plan and our requests for relief. Your immediate action on this item is appreciated.

Should you have any questions concerning this request, please contact Mr. P. L. Powell, Manager, WNP-2 Licensing.

Very truly yours,



G. C. Sorensen, Manager
Regulatory Programs

cc: JO Bradfute/NRC
MR Humm/NRC
JB Martin/Region V
E Revell/BPA
NS Reynolds/BLCP&R
NRC Site Inspector



1

1