

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8801130093 DOC. DATE: 87/12/22 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME AUTHOR AFFILIATION
 SORENSEN, G.C. Washington Public Power Supply System
 RECIP. NAME RECIPIENT AFFILIATION
 MARTIN, J.B. Region 5, Ofc of the Director

SUBJECT: Informs that detailed discussion of corrective actions will be included in response to Insp Rept 87-19 by 880205.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTTR 1 ENCL 0 SIZE: 1
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 PD	1 1	SAMWORTH, R	2 2
INTERNAL:	ACRS	2 2	AEOD	1 1
	DEDRO	1 1	NRR MORISSEAU, D	1 1
	NRR/DLPQ/PEB	1 1	NRR/DOEA DIR	1 1
	NRR/DREP/EPB	1 1	NRR/DREP/RPB	2 2
	NRR/DRIS DIR	1 1	NRR/PMAS/ILRB	1 1
	OE LIEBERMAN, J	1 1	OGC/HDS2	1 1
	REG FILE	1 1	RES DEPY GI	1 1
	RGN5-FILE 01	1 1		
INTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



WASHINGTON PUBLIC POWER SUPPLY SYSTEM

RECEIVED
NRC
REGION V

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

DEC 28 9 52

Docket No. 50-397

December 22, 1987

Mr. J. B. Martin, Regional Administrator
Region V, U.S. Nuclear Regulatory Commission
1450 Maria Lane, Suite 210
Walnut Creek, CA 94596-5368

Dear Mr. Martin:

Subject: NRC INSPECTION AT WNP-2
INSPECTION REPORT 87-19

Reference: Letter, JB Martin to GC Sorensen, same subject, dated December 18, 1987

The referenced letter transmitted to the Supply System the results of the Safety System Functional Inspection (SSFI) conducted by members of your staff and others on August 3 through 28, 1987.

The inspection report identified the objective of the SSFI as being "to assess the operational readiness of selected safety systems to function under all operational and analyzed accident conditions." We note that the inspection did not identify any deficiencies which would prevent the reviewed systems from performing their intended function.

However, the inspection did identify several deficiencies of lesser significance which we are taking steps to correct. The Supply System takes seriously its commitment to operational excellence and is in the process of establishing programs to correct the deficiencies identified in the SSFI.

A detailed discussion of the corrective actions to be taken will be included in our response to the inspection report. As agreed with members of your staff, we will respond to the inspection report by February 5, 1988.

Very truly yours,

GC Sorensen
G. C. Sorensen, Manager
Regulatory Programs

8801130093 871222
PDR ADOCK 05000397
Q BCD

