

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352-0968 • (509) 372-5000

July 15, 1994  
GO2-94-165

Docket No. 50-397

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Gentlemen:


Subject: **WNP-2, OPERATING LICENSE NPF-21**  
**LER 93-031-01 CORRECTIVE ACTIONS**

LER 93-031-01 reported the discovery of a performance analysis problem involving control room cooling. It had been found that the Standby Service Water System could not maintain the control room below its design temperature under accident conditions unless certain non-essential electrical loads were shed. Procedures did not contain direction to shed these loads.

A number of corrective actions were identified, and have been completed. One remaining action involved the review of heat transfer components cooled by Standby Service Water. The objective of this review is to determine if the components have been designed with adequate consideration of potential fouling. To date, potentially affected components have been identified, and the review has been completed for more than 50% of them. We are continuing our research, and will complete this action by July 29, 1994 as discussed with members of the Staff.

Should you have any questions or desire additional information regarding this matter, please call me or D. A. Swank, Manager, Compliance at (509) 377-4563.

Sincerely,



J. V. Parrish (Mail Drop 1023)  
Assistant Managing Director, Operations

cc: LJ Callan - NRC RIV  
NS Reynolds - Winston & Strawn  
DL Williams - BPA/399  
KE Perkins, Jr. - NRC RIV, Walnut Creek Field Office

JW Clifford - NRC  
NRC Sr. Resident Inspector - 927N

9407260060 940715  
PDR ADOCK 05000397  
S PDR



# PRIORITY 1

(ACCELERATED RIDS PROCESSING)

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9407260060      DOC. DATE: 94/07/15      NOTARIZED: NO      DOCKET #  
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe      05000397  
 AUTH. NAME      AUTHOR AFFILIATION  
 PARRISH, J.V.      Washington Public Power Supply System  
 RECIP. NAME      RECIPIENT AFFILIATION  
                          Document Control Branch (Document Control Desk)

SUBJECT: Provides info re WNP-2, Operating License NPF-21,  
 LER 93-031-01, corrective actions that were completed.

DISTRIBUTION CODE: IE22D      COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PDIV-3 PD	1	CLIFFORD, J	1
INTERNAL:	ACRS	1	AEOD/DSP/TPAB	1
	AEOD/ROAB/DSP	2	NRR/DE/EELB	1
	NRR/DE/EMEB	1	NRR/DORS/OEAB	1
	NRR/DRCH/HHFB	1	NRR/DRCH/HICB	1
	NRR/DRCH/HOLB	1	NRR/DRSS/PRPB	2
	NRR/DSSA/SPLB	1	NRR/DSSA/SRXB	1
	NRR/PMAS/IRCB-E	1	<u>REG FILE</u> 02	1
	RES/DSIR/EIB	1	RGN4 FILE 01	1
EXTERNAL:	EG&G BRYCE, J.H	2	L ST LOBBY WARD	1
	NRC PDR	1	NSIC MURPHY, G.A	1
	NSIC POORE, W.	1	NUDOCS FULL TXT	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL  
 DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM  
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR    27    ENCL    270

P  
R  
I  
O  
R  
I  
T  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T