

Central File

ARIZONA




PUBLIC SERVICE COMPANY

P. O. BOX 21666 • PHOENIX, ARIZONA 85036

July 10, 1980

ANPP-15885 - JMA/KWG

Docket Nos. 50-528, 50-529, 50-530



10/2

Mr. R. H. Engelken, Director
U.S. Nuclear Regulatory Commission
Region V
202 Walnut Creek Plaza
1990 N. California Boulevard
Suite 202, Walnut Creek Plaza
Walnut Creek, California 94596

Subject: NRC I&E Bulletin No. 79-03A
Longitudinal Weld Defects in ASME
SA-312, Type 304 Stainless Steel
Pipe
File: D.4.01.1

Dear Mr. Engelken:

In reference to I&E Bulletin No. 79-03A, which discussed longitudinal weld defects in SA-312/A-312 welded material, we request a 60 day extension to obtain additional information from our vendors as requested in the Bulletin.

Very truly yours,

E. E. Van Brunt

E. E. Van Brunt, Jr.
APS Vice President,
Nuclear Projects
ANPP Project Director

EEVBjr/KWG/av

cc: J. M. Allen
W. F. Quinn
W. H. Wilson
F. W. Hartley
J. Kerrigan
NRC Office of Inspection & Enforcement
Division of Reactor Inspection Programs
Washington, D.C. 20555

R

8009050499

80-56

