

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8505300140 DOC. DATE: 85/05/28 NOTARIZED: NO DOCKET #
 FACIL: STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Public 05000528
 AUTH. NAME AUTHOR AFFILIATION
 VAN BRUNT, E.E. Arizona Public Service Co.
 RECIP. NAME RECIPIENT AFFILIATION
 KNIGHTON, G.W. Licensing Branch 3

SUBJECT: Confirms completion of actions taken to correct listed Suppl
 1 to NUREG-0737, human engineering discrepancies re control
 room design review described in 841029 ltr. License Condition
 2.C(19)(b) closed.


DISTRIBUTION CODE: A003D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR/Licensing Submittal: Suppl 1 to NUREG-0737 (Generic Ltr 82-33)

NOTES: Standardized plant.
 OL: 12/31/84

05000528

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	NRR LB3 BC	7		
INTERNAL:	ADM/LFMB	1	IE/DEPER/EPB	3
	NRR PAULSON, W	1	NRR/DHFS/HFEB	5
	NRR/DHFS/PSRB	2	NRR/DL/ORAB	1
	NRR/DL/ORBS	5	NRR/DSI/CPB	1
	NRR/DSI/ICSB	1	NRR/DSI/METB	1
	NRR/DSI/RAB	1	NRR/DSI/RSB	1
	<u>REG FILES</u>	1	RGNS	1
EXTERNAL:	LPDR	1	NRC PDR	1
	NSIC	1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 35 ENCL 34





Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

Director of Nuclear Reactor Regulation
Attention: Mr. George W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ANPP-32741-EEVB/MAJ
May 28, 1985

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Condition 2.(19)(b) Supplement 1 to NUREG-0737=Human
Engineering Discrepancies (HED's)
Docket No. STN 50-528 (License No. NPF-34)
File: 85-056-026; G.1.01.10

Reference: Letter to G. W. Knighton, NRC, from
E.E. Van Brunt, Jr., APS, dated October
29, 1984 (ANPP-30986). Subject: Control
Room Design Review.

Dear Mr. Knighton:

License Condition 2.C(19)(b) states: "Prior to exceeding 5% of full power, APS shall implement actions to correct HED's A-3.1, 173, 151A, 152A, 154A, 158A, 161A, 163A, 164A, 159B, 165A, 166A, and 153A as described in its submittal of October 29, 1984."

In accordance with License Condition 2.C(19)(b), we hereby confirm completion of the actions taken to correct the subject HED's as described in our October 29, 1984 letter. This completes the action items required to close out License Condition 2.C(19)(b).

If you have any questions, please call William Quinn of my staff at extension 4087.

Very truly yours,

8505300140 850528
PDR ADDCK 05000528
F PDR

E.E. Van Brunt
E. E. Van Brunt, Jr.
Executive Vice President
Project Director

EEVB/MAJ/mkm

cc: A. C. Gehr
E. Licitra
R. Zimmerman
G. Fiorelli

A003
1/0

G. W. Knighton
Human Engineering Discrepancies
Page 2
ANPP - 32741

bcc: D. B. Karner
W. F. Quinn
T. F. Quan
J. W. Rowland
LCTS Coordinator
K. W. Gross
J. M. Allen
J. R. Bynum
D. R. Canady
O. J. Zeringue
G. Sanchez
A. C. Rogers



10-11-54