

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9105280125 DOC.DATE: 91/05/14 NOTARIZED: NO DOCKET #
 FACIL:STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530
 AUTH.NAME AUTHOR AFFILIATION
 LEVINE,J.M. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP.NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Forwards Special Rept 3-SR-91-002, "Steam Generator Eddy
 Current Exam Second Refueling Outage."

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+17
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:Standardized plant.

05000530

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	PD5 LA	1	0	PD5 PD	1	1
	TRAMMELL,C	2	2	THOMPSON,M	2	2
INTERNAL:	ACRS	6	6	AEOD/DSP/TPAB	1	1
	NRR/DET/ECMB 9H	1	1	NRR/DET/EMEB 7E	1	1
	NUDOCS-ABSTRACT	1	1	OC/LEMB	1	0
	OGC/HDS1	1	0	REG FILE 01	1	1
	RES/DSIR/EIB	1	1			
EXTERNAL:	EG&G BROWN,B	1	1	EG&G RANSOME,C	1	1
	NRC PDR	1	1	NSIC	1	1
NOTES:		1	1			

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 22

IA2

2342 2491

2342 2491

2342 2491

2342 2491

2342 2491

2342 2491

2342 2491

2342 2491

2342 2491

2342 2491

2342 2491

Arizona Public Service Company

PALO VERDE NUCLEAR GENERATING STATION
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

JAMES M. LEVINE
VICE PRESIDENT
NUCLEAR PRODUCTION

192-00721-JML/TRB/KR

May 14, 1991

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555


Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 3
Docket No. STN 50-530 (License No. NPF-74)
Special Report 3-SR-91-002
File: 91-020-404

Attached please find Special Report 3-SR-91-002 prepared and submitted pursuant to Technical Specifications 3.4.4 and 6.9.2. This report discusses the complete results of the Steam Generator Tube Inservice Inspection and satisfies the requirements of Technical Specification 4.4.4.5.b.

If you have any questions, please contact T. R. Bradish, Compliance Manager at (602) 393-2521.

Very truly yours,



JML/TRB/KR/nk

Attachment

cc: W. F. Conway (all with attachment)
J. B. Martin
D. H. Coe
A. C. Gehr
A. H. Gutterman

9105280125 910514
PDR ADCK 05000530
Q PDR

AOA7
11

bcc: J. M. Levine 6125
J. N. Bailey 1966
W. E. Ide 7194
R. K. Flood 7294
R. J. Adney 7394
R. F. Schaller 7194
T. D. Shriver 7294
J. J. Scott 7394
F. W. Riedel 7198
P. J. Wiley 7298
M. L. Clyde 7398
Source Document File 6715
PRS File: N/A
B. E. Ballard 6128
R. J. Stevens 1502
E. E. Van Brunt 1922
R. E. Gouge 6123
E. G. Firth (Training) 6155
R. C. Fullmer 6795
G. T. Shell 6794
M. R. Oren (STA) 6079
D. N. Stover (NSD) 1536
J. R. LoCicero (ISEG) 6144
R. W. Page 1938
D. B. Andrews 6345
M. E. Powell 1515
A. C. Rogers 1502
S. A. Gallinger 6934
P. J. Coffin 6148
B. A. Brown 6148
R. A. Jourdonnais 1686
R. G. Hogstrom 6086
Responsible Department (required review):
G. R. Overbeck 6102
W. E. Webster 6045
D. B. Hansen 6086
Compliance Supervisor
Compliance Manager

