

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9204280349 DOC.DATE: 92/04/18 NOTARIZED: NO DOCKET #
 FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528
 AUTH.NAME AUTHOR AFFILIATION
 LEVINE,J.M. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special Rept SR-92-002:on 920411,insp of SGs resulted in
 plugging of 23 tubes in SG 1 & 18 tubes in SG 2.Complete
 results of SG tube ISI will be submitted by 930411.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:STANDARDIZED PLANT

05000528 /

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL	
	PD5 LA		1	1		PD5 PD		1	1	
	TRAMMELL,C		1	1		THOMPSON,M		1	1	
INTERNAL:	ACNW		2	2		ACRS		2	2	
	AEOD/DOA		1	1		AEOD/DSP/TPAB		1	1	
	AEOD/ROAB/DSP		2	2		NRR/DET/EMEB 7E		1	1	
	NRR/DLPQ/LHFB10		1	1		NRR/DLPQ/LPEB10		1	1	
	NRR/DOEA/OEAB		1	1		NRR/DREP/PRPB11		2	2	
	NRR/DST/SELB 8D		1	1		NRR/DST/SICB8H3		1	1	
	NRR/DST/SPLB8D1		1	1		NRR/DST/SRXB 8E		1	1	
	REG FILE 02		1	1		RES/DSIR/EIB		1	1	
	RGN5 FILE 01		1	1						
EXTERNAL:	EG&G BRYCE,J.H		3	3		L ST LOBBY WARD		1	1	
	NRC PDR		1	1		NSIC MURPHY,G.A		1	1	
	NSIC POORE,W.		1	1		NUDOCS FULL TXT		1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 33

Arizona Public Service Company
PALO VERDE NUCLEAR GENERATING STATION
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

JAMES M. LEVINE
VICE PRESIDENT
NUCLEAR PRODUCTION

192-00781-JML/TRB/KR
April 18, 1992

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Docket No. STN 50-528 (License No. NPF-41)
Special Report 1-SR-92-002
File: 92-020-404

Attached please find Special Report 1-SR-92-002 prepared and submitted pursuant to Technical Specifications 4.4.4.5 and 6.9.2. This report discusses steam generator tube plugging in Unit 1. A copy of the Special Report is being forwarded to the Regional Administrator, NRC Region V.

If you have any questions, please contact T. R. Bradish, Compliance Manager, at (602) 393-5421.

Very truly yours,

James M. Levine

JML/TRB/KR

Attachment

cc: W. F. Conway (all with attachment)
J. B. Martin
D. H. Coe

9204280349 920418
PDR ADOCK 05000528
S PDR

JE 22

Palo Verde Nuclear Generating Station Unit 1

Steam Generator Tube Plugging

Docket No. STN 50-528

License No. NPF-41

Special Report No. 1-SR-92-002

This Special Report is being provided pursuant to Palo Verde Unit 1 Technical Specification TS 4.4.4.5(a) and TS 6.9.2 to report the number of steam generator tubes plugged as a result of inservice inspection activities. On April 11, 1992, Unit 1 was in a refueling outage with the core off-loaded to the Spent Fuel Pool when an inservice inspection of both steam generators was completed. The inspection resulted in the plugging of 23 tubes in Steam Generator No. 1 and 18 tubes in Steam Generator No. 2.

Pursuant to Technical Specification 4.4.4.5(b), the complete results of the steam generator tube inservice inspection will be submitted by April 11, 1993.