

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9304050276 DOC.DATE: 93/03/24 NOTARIZED: NO DOCKET #
 FACIL:STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530
 AUTH.NAME AUTHOR AFFILIATION
 LEVINE,J.M. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Palo Verde Nuclear Generating Station Unit 3 SG
 Eddy Current Exam,3rd Refueling Outage,Oct 1992." Rept
 discusses complete results of SG tube ISI.

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1476
 TITLE: OR Submittal: Inservice/Testing/Relief From ASME Code

NOTES:Standardized plant.

05000530

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 0	PD5 PD	1 1
	TRAMMELL,C	2 2	TRAN,L	2 2
INTERNAL:	ACRS	6 6	NRR/DE/EMEB	1 1
	NUDOCS-ABSTRACT	1 1	OC/LFMB	1 0
	OGC/HDS1	1 0	REG FILE 01	1 1
	RES MILLMAN,G	1 1	RES/DSIR/EIB	1 1
EXTERNAL:	EG&G BROWN,B	1 1	EG&G RANSOME,C	1 1
	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 20

Arizona Public Service Company

PALO VERDE NUCLEAR GENERATING STATION
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

JAMES M. LEVINE
VICE PRESIDENT
NUCLEAR PRODUCTION

192-00836-JML/TRB/KR
March 24, 1993

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555


Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 3
Docket No. STN 50-530 (License No. NPF-74)
Special Report 3-SR-93-002
File: 93-020-404

Attached please find Special Report 3-SR-93-002 prepared and submitted pursuant to Technical Specification (TS) Surveillance Requirement 4.4.4.5.b and TS 6.9.2. This report discusses the complete results of the Steam Generator Tube Inservice Inspection. A copy of the Special Report is being forwarded to the Regional Administrator, NRC Region V.

If you have any questions, please contact T. R. Bradish, Manager, Nuclear Regulatory Affairs, at (602) 393-5421.

Sincerely,



JML/TRB/KR

050056

Attachment

cc: W. F. Conway (all with attachment)
J. B. Martin
J. A. Sloan

9304050276 930324
PDR ADDCK 05000530
Q PDR

AO47, 1/1

30-0000