

# ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9304190065      DOC. DATE: 93/04/13      NOTARIZED: NO      DOCKET #  
 FACIL: STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi      05000529  
 AUTH. NAME      AUTHOR AFFILIATION  
 LEVINE, J.M.      Arizona Public Service Co. (formerly Arizona Nuclear Power  
 RECIP. NAME      RECIPIENT AFFILIATION  
                          Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 93-001-00 re manual reactor trip due to steam generator tube rupture & valid actuation of safety injection actuation sys & containment isolation actuation sys. LER also describes actuation of ECCS.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTTR 1 ENCL 1 SIZE: 1+14  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Standardized plant.

05000529

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	ONDD LA	1 1	ONDD PD	1 1
	TRAMMELL, C	1 1	TRAN, L	1 1
INTERNAL:	ACNW	2 2	ACRS	2 2
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DORS/OEAB	1 1
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOLB	1 1	NRR/DRIL/RPEB	1 1
	NRR/DRSS/PRPB	2 2	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGN5 FILE 01	1 1
EXTERNAL:	EG&G BRYCE, J.H	2 2	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MURPHY, G.A	1 1
	NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 33



Arizona Public Service Company  
PALO VERDE NUCLEAR GENERATING STATION  
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

JAMES M. LEVINE  
VICE PRESIDENT  
NUCLEAR PRODUCTION

192-00837-JML/TRB/NLT  
April 13, 1993

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Mail Station P1-37  
Washington, D.C. 20555

Dear Sirs:


Subject: Palo Verde Nuclear Generating Station  
Unit 2  
Docket No. STN 50-529 (License No. NPF-51)  
Licensee Event Report 93-001-00  
File: 93-020-404

Attached please find Licensee Event Report (LER) 93-001-00 prepared and submitted pursuant to 10CFR50.73. This LER reports a Unit 2 manual reactor trip due to a steam generator tube rupture, and a valid actuation of the Safety Injection Actuation System and the Containment Isolation Actuation System. In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region V.

Pursuant to Technical Specification 3.5.2, ACTION b, this LER also describes the actuation of the Emergency Core Cooling System, and satisfies the Special Report requirements for documenting the total accumulated actuation cycles to date for Unit 2.

If you have any questions, please contact T. R. Bradish, Manager, Nuclear Regulatory Affairs at (602) 393-5421.

Very truly yours,



JML/TRB/nlt

Attachment

cc: W. F. Conway (all with attachment)  
J. B. Martin  
J. A. Sloan  
INPO Records Center

9304170065 930413  
PDR ADDCK 05000529  
S PDR

190032

JE72 1

