

(CAR 1296)

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	-----

1 6

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	R	E	G	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	4	57	CAT	58		5

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	2	4	4	7	0	3	2	3	8	1	8	0	4	2	2	8	1	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During operator tour leakage was seen at immediate borate valve outlet piping

03 | (T.S. 6.9.2.b(4). Line was immediately isolated for repair. Two flow paths from

04 | boric acid tanks remained operable.

0	5
---	---

0	6	
---	---	--

0	7	
---	---	--

08 | _____ 8

0 9
 2 8

SYSTEM CODE
 P C 11
 9 10

CAUSE CODE
 E 12
 11

CAUSE SUBCODE
 D 13
 12

COMPONENT CODE
 P I P E X X 14
 13 18

COMP. SUBCODE
 A 15
 19

VALVE SUBCODE
 Z 16
 20

(17) LER/RO REPORT NUMBER	EVENT YEAR [8 1] 21 22	[—] 23	SEQUENTIAL REPORT NO. [0 0 6] 24 25 26	[/] 27	OCCURRENCE CODE [0 3] 28 29	REPORT TYPE [L] 30	[—] 31	REVISION NO. [0] 32
ACTION TAKEN [Z] (18)	FUTURE ACTION [A] (19)	EFFECT ON PLANT [Z] (20)	SHUTDOWN METHOD [Z] (21)	HOURS [0 0 0 0] 37 38 39 40	(22) ATTACHMENT SUBMITTED [N] (23)	NPRD-4 FORM SUB. [N] (24)	PRIME COMP. SUPPLIER [N] (25)	COMPONENT MANUFACTURER [B 1 3 0] (26) 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Possible stress corrosion cracking. Examination showed family of cracks on exterior

[11] , surface, some thru-wall. Pipe section was removed for metallurgical analysis to

1 2 | confirm cause. With unit in AI&O all similar areas of piping will be inspected. Pipe

13 | is 150 psi sch 10 304 SS containing 12% boric acid.

1 4

7 8 9

80

FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)		
1	5	E	28	1	0 0	29	NA	B	31	Operator tour
7	8	9	10	11	12	13	44	45	46	80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES		DESCRIPTION	
NUMBER	TYPE		
000	Z	NA	

PERSONNEL INJURIES		DESCRIPTION	
1	3	40	NA
0	0	0	

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA

ISSUED 20 PUBLICITY DESCRIPTION NA 8104280509 NRC USE ONLY

NAME OF PREPARER S. M. Spector

PHONE: 315-524-4446, ext. 214

017-926

