

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9407220157 DOC. DATE: 94/07/19 NOTARIZED: NO DOCKET #
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
 AUTH. NAME AUTHOR AFFILIATION
 SAGER, D.A. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

See Reports

SUBJECT: Forwards Rev 0 to PSL-200-SR-94, "Second ISI Interval First Insp Period First Outage 1994 Summary Rept Submittal for St Lucie Unit 2."

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+300
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		L	T		ID CODE/NAME		L	T
	PD2-2 LA		1	0		PD2-2 PD		1	1
	NORRIS, J		2	2					
INTERNAL:	ACRS		6	6		AEOD/DSP/ROAB		1	1
	NRR/DE/EMEB		1	1		NRR/EMCB		1	1
	NUDOCS-ABSTRACT		1	1		OC/LFDCB		1	0
	OGC/HDS3		1	0		REG-FILE 01		1	1
	RES/DSIR/EIB		1	1					
EXTERNAL:	EG&G BROWN, B		1	1		EG&G RANSOME, C		1	1
	NRC PDR		1	1		NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 19



100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000



P.O. Box 128, Ft. Pierce, FL 34954-0128

July 19, 1994

L-94-187
10 CFR 50.55a
10 CFR 50.36

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Re: St. Lucie Unit 2
Docket No. 50-389
1994 Spring Refueling Outage
Inservice Inspection Reports

Enclosed are the ASME Section XI Inservice Inspection Reports for St. Lucie Unit 2 1994 spring refueling outage. Enclosure 1 is the NIS-1 Inservice Inspection Reports. Enclosure 2 is the NIS-2 Owner's Reports of Repairs and Replacements. The Forms NIS-1 and NIS-2 Inservice Inspection Summary Reports are required by ASME Code Section XI. The reports are to be submitted within 90 days of completing the refueling outage inservice inspection.

This report provides the information required to be included in the Steam Generator Tube Inservice Inspection Special Report. The report is being included pursuant to sections 4.4.5.5.b and 6.9.2 of the St. Lucie Unit 2 Technical Specifications.

Should there be any questions, please contact us.

Very truly yours,

C. L. Burton for
D. A. Sager
Vice President
St. Lucie Plant

DAS/CDW/kw

Enclosures

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL#1166-94

220063

9407220157 940719
PDR ADOCK 05000389
Q PDR

an FPL Group company

AD471

Re: St. Lucie Unit 2
Docket No. 50-389
1994 Spring Refueling Outage
Inservice Inspection Reports

ENCLOSURE 1

NIS-1 Inservice Inspection Reports

07/19/94....9407220157