

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9401280112 DOC. DATE: 94/01/13 NOTARIZED: NO DOCKET #
 FACIL: STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529
 STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530
 AUTH. NAME AUTHOR AFFILIATION
 LEVINE, J.M. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards Suppl 2 to Special Repts 2-SR-92-004 & 3-SR-92-006
 re post accident sampling sys being inoperable for greater
 than seven days for Units 2 & 3, respectively.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTTR 1 ENCL 1 SIZE: 2+7
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Standardized plant.
 Standardized plant.

05000529
 05000530

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PDV LA	1 1	PDV PD	1 1
HOLIAN, B	1 1	TRAN, L	1 1
INTERNAL: ACRS.	2 2	AEOD/DOA	1 1
AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
NRR/DORS/OEAB	1 1	NRR/DRCH/HHFB	1 1
NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
NRR/DRIL/RPEB	1 1	NRR/DRSS/PRPB	2 2
NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
REG FILE 02	1 1	RES/DSIR/EIB	1 1
RGN5 FILE 01	1 1		
EXTERNAL: EG&G BRYCE, J.H	2 2	L ST LOBBY WARD	1 1
NRC PDR	1 1	NSIC MURPHY, G.A	1 1
NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

Arizona Public Service Company

PALO VERDE NUCLEAR GENERATING STATION
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00880-JML/BAG/PMM

January 13, 1994

JAMES M. LEVINE
VICE PRESIDENT
NUCLEAR PRODUCTION

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555


Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 2 and 3
Docket Nos. STN 50-529 and 50-530
License Nos. NPF-51 and NPF-74
Supplement 2 to Special Reports
2-SR-92-004 and 3-SR-92-006
File: 94-020-404

Enclosed is Supplement 2 to Special Reports 2-SR-92-004 and 3-SR-92-006 prepared and submitted pursuant to Technical Specification (TS) 3.3.3.1 ACTION 28 and TS 6.9.2. This supplement is being submitted to update the corrective actions listed in Enclosure 2.

If you have any questions, please contact Burton A. Grabo, Supervisor, Nuclear Regulatory Affairs at (602) 393-6492.

Sincerely,



JML/BAG/PMM/pm

Enclosures:

1. Special Reports 2-SR-92-004-02 and 3-SR-92-006-02
2. Cause of Post Accident Sampling System Inoperability

cc: W. F. Conway (all with enclosures)
K. E. Perkins
K. E. Johnston

9401280112 940113
PDR ADCK 05000529
S PDR

Test 1

ENCLOSURE 1

SPECIAL REPORTS 2-SR-92-004-02 AND 3-SR-92-006-02

