

# PRIORITY 1

(ACCELERATED RIDS PROCESSING)

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9408230112      DOC. DATE: 94/08/11      NOTARIZED: NO      DOCKET #  
 FACIL: STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528  
          STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529  
          STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530

AUTH. NAME      AUTHOR AFFILIATION  
 STEWART, W.L.      Arizona Public Service Co. (formerly Arizona Nuclear Power  
 RECIP. NAME      RECIPIENT AFFILIATION  
                          Document Control Branch (Document Control Desk) *See Reports*

SUBJECT: Forwards Unit 2 SG IR from last mid cycle outage. APS stated that it would present, within four & one half months of breaker closure, final regulatory guide 1.121 evaluation results of pulled tube analyses & statistical treatment.

DISTRIBUTION CODE: A001D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 14-105  
 TITLE: OR Submittal: General Distribution

NOTES: STANDARDIZED PLANT'      05000528  
          Standardized plant.      05000529  
          Standardized plant.      05000530


RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD4-2 LA	1    1	PD4-2 PD	1    1
HOLIAN, B	2    2	TRAN, L	2    2
INTERNAL: ACRS	6    6	NRR/DE/EELB	1    1
NRR/DORS/ONDD	1    1	NRR/DRCH/HICB	1    1
NRR/DRPW	1    1	NRR/DSSA/SPLB	1    1
NRR/DSSA/SRXB	1    1	NUDOCS-ABSTRACT	1    1
<u>OC/LFDCB</u>	1    0	OGC/HDS2	1    0
REG FILE      01	1    1		
EXTERNAL: NOAC	1    1	NRC PDR	1    1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR    24    ENCL    22

MA



Arizona Public Service Company  
P.O. BOX 53999 • PHOENIX, ARIZONA 85072-3999

WILLIAM L. STEWART  
EXECUTIVE VICE PRESIDENT  
NUCLEAR

102-03083-WLS/AKK/JRP  
August 11, 1994

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-37  
Washington, D.C. 20555

Reference: Letter No. 102-02852, dated March 8, 1994, from W. F. Conway, Executive Vice President, Nuclear, APS, to USNRC.

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)  
Units 1, 2 and 3  
Docket No. STN 50-528, 50-529, 50-530  
Status of PVNGS Steam Generator Activities  
File: 94-056-026

The referenced letter transmitted the Unit 2 Steam Generator Inspection Report from the last mid-cycle outage. In that letter, Arizona Public Service Company (APS) stated that it would present, within four and one half months of breaker closure, a final Regulatory Guide 1.121 evaluation, results of the pulled tube analyses, and a statistical treatment of uncertainties.

The enclosed report provides 1) the results of Units 2 and 3 metallurgical tube examinations, 2) results of probabilistic Regulatory Guide 1.121 assessments for Units 1 and 2, and 3) details of the PVNGS integrated outage assessment program.

Should you have any questions, please contact Scott A. Bauer at (602) 393-5978.

Sincerely,



WLS/AKK/JRP/dpr

Enclosure: Status of PVNGS Steam Generator Activities

cc: L. J. Callan  
K. E. Perkins  
K. E. Johnston  
B. E. Holian  
I. Barnes

9408230112 940811  
PDR ADOCK 05000528  
P PDR

*Adol*  
11/11



1

2

3

4

5

6

7

8

9

10