

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9508230038 DOC.DATE: 95/08/16 NOTARIZED: NO DOCKET #
FACIL:STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529 P
AUTH.NAME AUTHOR AFFILIATION
LEVINE,J.M. Arizona Public Service Co. (formerly Arizona Nuclear Power R
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 95-005 re RT on low SG water level following
degradation of MFW flow. I

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 147 O
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc. R

NOTES:Standardized plant.

05000529

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD4-2 PD	1 1	HOLIAN, B	1 1	T
	TRAN, L	1 1			Y
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2	
	AEOD/SPD/RRAB	1 1	FILE CENTER	1 1	
	NRR/DE/ECGB	1 1	NRR/DE/EEEB	1 1	1
	NRR/DE/EMEB	1 1	NRR/DISP/PIPB	1 1	
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1	
	NRR/DRCH/HOLB	1 1	NRR/DRPM/PECB	1 1	
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SPSB/B.	1 1	D
	NRR/DSSA/SRXB	1 1	RES/DSIR/EIB	1 1	
	RGN4 FILE 01	1 1			O
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	2 2	
	NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1	C
	NRC PDR	1 1	NUDOCS FULL TXT	1 1	U

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 28 ENCL 28

A0-4

Arizona Public Service Company

PALO VERDE NUCLEAR GENERATING STATION
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00943-JML/BAG/BE

August 16, 1995

JAMES M. LEVINE
VICE PRESIDENT
NUCLEAR PRODUCTION

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001


Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 2
Docket Nos. STN 50-529
License Nos. NPF-51
Licensee Event Report 95-005-00

Attached please find Licensee Event Report (LER) 95-005 prepared and submitted pursuant to 10CFR50.73. This LER reports a July 17, 1995, reactor trip on low steam generator water level following the degradation of main feedwater flow. The unit also received an Engineered Safety Feature Actuation System (ESFAS) actuation of the Auxiliary Feedwater Actuation System on low steam generator level and an Emergency Diesel Generator start on loss of power to the Class 1E 4.16 kV bus. In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV.

If you have any questions, please contact Burton A. Grabo, Section Leader, Nuclear Regulatory Affairs, at (602) 393-6492.

Sincerely,



JML/BAG/BE/pv

Attachment

cc: L. J. Callan (all with attachment)
K. E. Perkins
K. E. Johnston
INPO Records Center

9508230038 950816
PDR ADDCK 05000529
S PDR

