

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SUBJECT: Forwards "PVNGS Unit 1 Inservice Insp Rept Seventh Refueling Outage," per 10CFR50.55a.

NOTES: STANDARDIZED PLANT

05000528

	RECIPIENT	COPIES			RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR	ENCL
	PD4-2 LA	1	1		PD4-2 PD	1	1
	FIELDS,M	1	1				
INTERNAL:	ACRS	1	1		AEOD/SPD/RAB	1	1
	FILE CENTER 01	1	1		NRR/DE/ECGB	1	1
	NUDOCS-ABSTRACT	1	1		OGC/HDS2	1	0
	RES/DET/EIB	1	1		RES/DET/EMMEB	1	1
EXTERNAL:	LITCO ANDERSON	1	1		NOAC	1	1
	NRC PDR	1	1				

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 13

MA2



Palo Verde Nuclear
Generating Station

William E. Ide
Vice President
Nuclear Engineering

TEL 602/393-6116
FAX 602/393-6077

Mail Station 7605
P.O. Box 52034
Phoenix, AZ 85072-2034

102-04149-WEI/AKK/MLG
July 15, 1998

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Docket No. STN 50-528
Unit 1 Inservice Inspection Report Seventh Refueling Outage**

Pursuant to 10CFR50.55a, enclosed please find the PVNGS Unit 1 Inservice Inspection Report for the seventh refueling outage.

If you have any questions, please contact Scott A. Bauer at (602) 393-5978.

Sincerely,

WEI/AKK/MLG/rlh

Enclosure

cc: E. W. Merschoff
K. E. Perkins
M. B. Fields
J. H. Moorman

11
A047

9807220205 980715
PDR ADDCK 05000528
Q PDR

