

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SUBJECT: Forwards LER 98-007-01 re letdown leak that required entry into TS LCO 3.0.3. LER contains specific commitments for correcting condition.

NOTES: STANDARDIZED PLANT


05000528E

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED .
TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

A04





Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01031-GRO/DGM/RJH
September 25, 1998

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS) Unit 1
Docket No. STN 50-528,
License No. NPF-41,
Licensee Event Report 98-007-01**

Attached please find Supplement 1 to Licensee Event Report (LER) 98-007-00 prepared and submitted pursuant to 10 CFR 50.73. This LER reports a condition where a letdown line leak in Unit 1 required entry into Technical Specification LCO 3.0.3. The LER contains specific commitments for correcting the condition.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

GRO/DGM/RJH/rh

Attachment

cc: E. W. Merschoff (all with attachment)
J. H. Moorman
INPO Records Center

9810060043 980925
PDR ADOCK 05000528
S PDR

