

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9903020174 . DOC.DATE: 99/02/18 NOTARIZED: NO DOCKET #  
FACIL:STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530  
AUTH.NAME AUTHOR AFFILIATION  
OVERBECK, G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power  
RECIP.NAME RECIPIENT AFFILIATION  
Records Management Branch (Document Control Desk) *See*

SUBJECT: Forwards "PVNGS Unit 3 7th Refueling Outage," which provides complete results of SG tube inservice insp performed., per TS 5.6.8. C

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 200  
TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES: Standardized plant. 05000530E

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
PD4-2	LA	1	1	PD4-2	PD	1	1
	FIELDS, M	1	1				
INTERNAL:	ACRS	1	1		AEOD/SPD/RAB	1	1
	<del>ELLE-GENTER-040</del>	1	1		NRR/DE/ECGB	1	1
	NUDOCS-ABSTRACT	1	1		OGC/HDS2	1	0
	RES/DET/EIB	1	1		RES/DET/EMMEB	1	1
EXTERNAL:	LITCO ANDERSON	1	1		NOAC	1	1
	NRC PDR	1	1				

NOTE TO ALL "RIDS" RECIPIENTS:  
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
DESK (DCD) ON EXTENSION 415-2083

**TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 13**





Palo Verde Nuclear  
Generating Station

Gregg R. Overbeck  
Vice President  
Nuclear Production

TEL 602/393-5148  
FAX 602/393-6077

Mail Station 7602  
P.O. Box 52034  
Phoenix, AZ 85072-2034

192-01039-GRO/DGM/REB  
February 18, 1999

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-37  
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS) Unit 3  
Docket No. STN 50-530,  
License No. NPF-74,  
Special Report 3-SR-98-001**

Pursuant to PVNGS Technical Specification 5.6.8, enclosed is Supplement 1 to Special Report 3-SR-98-001. This supplement provides the complete results of the steam generator tube inservice inspection that was performed during the Unit 3 seventh refueling outage.

By copy of this letter and the enclosure, this Special Report is being provided to the NRC Region IV Administrator and the PVNGS Senior Resident Inspector.

This letter does not make any commitments to the NRC. Please contact Daniel G. Marks at (602) 393-6492 if you have any questions or require additional information.

Sincerely,

*Gregg R. Overbeck*

GRO/DGM/REB/mah

Enclosure

cc: E. W. Merschhoff (all with enclosure)  
M. B. Fields  
J. H. Moorman  
P. H. Harrell

9903020174 990218  
PDR ADDCK 05000530  
G PDR

010063

1/1  
A047

