

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9907280248 DOC.DATE: 99/07/16 NOTARIZED: NO DOCKET #  
 FACIL:STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529  
 AUTH.NAME AUTHOR AFFILIATION  
 OVERBECK,G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power  
 RECIP.NAME RECIPIENT AFFILIATION  
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-005-00, re automatic RT which occurred on  
 990618, following sensor failure in core protection  
 calculators. Corrective actions described in LER are not  
 necessary to maintain compliance with regulations.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+5  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:Standardized plant.

05000529

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	LPD4-2	1 1	FIELDS,M	1 1
INTERNAL:	ACRS	1 1	<u>FILE CENTER</u>	1 1
	NRR/DIPM/IOLB	1 1	NRR/DRIP/REXB	1 1
	NRR/DSSA/SPLB	1 1	RES/DET/ERAB	1 1
	RES/DRAA/OERAB	1 1	RGN4 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LMITCO MARSHALL	1 1
	NOAC POORE,W.	1 1	NOAC QUEENER,DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIS  
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTR  
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 16

104





Palo Verde Nuclear  
Generating Station

Gregg R. Overbeck  
Vice President  
Nuclear Production

TEL 602/393-5148  
FAX 602/393-6077

Mail Station 7602  
P.O. Box 52034  
Phoenix, AZ 85072-2034

192-01051-GRO/DGM/DLK  
July 16, 1999

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-37  
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)**  
**Unit 2**  
**Docket No. STN 50-529**  
**License No. NPF-51**  
**Licensee Event Report 99-005-00**

Attached please find Licensee Event Report (LER) 50-529/99-005-00 prepared and submitted pursuant to 10 CFR 50.73. This LER reports an automatic reactor trip which occurred on June 18, 1999 following sensor failures in the core protection calculators. The reactor trip was classified as uncomplicated. The corrective actions described in this LER are not necessary to maintain compliance with regulations and are therefore not regulatory commitments.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have questions regarding this submittal, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (623) 393-6492.

Sincerely,

9907280248 990716  
PDR ADDCK 05000529  
S PDR

GRO/DGM/DLK

Attachment

cc: E. W. Merschoff (all with attachment)  
P. H. Harrell  
J. H. Moorman  
N. Kalyanam  
INPO Records Center

280008

JE 22

