

A002

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-316 COOK -2
RECIPIENT: KEPPLER, J.G.
ORIGINATOR: SHALLER, D.V.
COMPANY NAME: IN & MI PWR CO
SUBJECT:

DOC DATE: 781101
ACCESSION NBR: 7811090151
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+2

LER#78-076/03L-0 on 781003: surveillance tests on train-B of solid st
protec sys showed that several switch positions were bad. Caused by bad
universal logic card. Card replaced & sys returned to SVC.
LER#78-077/03L-0 encl.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED _____

NAME	ENCL?
BR CHIEF	W/4 ENCL
<u>REG FILE</u>	W/ENCL
NRC PDR	W/ENCL
I & E	W/3 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

NOV 14 1978

TOTAL NUMBER OF COPIES REQUIRED:
LTR
ENCL

42
42

NOTES: SEND 3 CYS OF ALL MATL TO I & E

As 4
60

D. Larkhan



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

November 1, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following reports are submitted:

RO 78-076/03L-0
RO 78-077/03L-0

Sincerely,

for D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
Dir., IE (30 copies)
Dir., MIPC (3 copies)

DUPES:

NOV 3 1978

7811090151 S 7811090158 S
7811090153 S

A002/s*
1/1



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

November 1, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following reports are submitted:

RO 78-076/03L-0
RO 78-077/03L-0

Sincerely,

for D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
Dir., IE (30 copies)
Dir., MIPC (3 copies)

REGULATORY DOCKET FILE COPY

7811090151

Acc 2
S 11