

Ad 2

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-316 COOK2
RECIPIENT: Keppler, J.G.
ORIGINATOR: Shaller, D.V.
COMPANY NAME: IN & MI PWR
SUBJECT:

DOC DATE: 781108
ACCESSION NBR: 7811140210
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+5

LER#78-034/03X-2 on 780515:Hydrogen skimmer recirculation fans starting times were found to be 10 minutes-6 seconds for 2HV-CEQ2 and 10 minutes-5 seconds for 2-HV-CEQ1. One minute TS tolerance for Unit#2 and agastats are of 0-6- minute range. (LER#78-078/03L-0 and #78-079/03L-0) encl)

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED _____

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
MRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:

LTR
ENCL

42
42

NOTES: Send 3 cys of all matl to I&E.

NOV. 16 1978

Ad. 4
60

REGULATORY DOCKET FILE COPY



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

November 8, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following reports are submitted:

RO 78-034/03X-2
RO 78-078/03L-0
RO 78-079/03L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
J.M. Hennigan
G. Olson
PNSRC
J.F. Stietzel
Dir., IE (30 copies)
Dir., MIPC (3 copies)

7811140210

1002
5/11