

A002

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-315 COOK 1  
RECIPIENT: KEPPLER, J.G.  
ORIGINATOR: SHALLER, D.V.  
COMPANY NAME: IN & MI PWR  
SUBJECT:

DOC DATE: 781115  
ACCESSION NBR: 7811210271  
COPIES RECEIVED:  
LTR 1 ENCL 1  
SIZE: 1+1

LER#78-060/03L-0 on 781028: RCS leak due to excessive packing on aa 3/4 valve in PZR safety valve loop seal drain line. Valve found to be 1/8 turn open. Valve closed & leakage stopped.

DISTRIBUTION CODE: A002  
DISTRIBUTION TITLE:  
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION  
ORB#1 BC

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

TOTAL NUMBER OF COPIES REQUIRED:  
LTR  
ENCL


42  
42

NOV 22 1978

NOTES: I & E - 3 CYS ALL MATERIAL

A0 4  
GP





**INDIANA & MICHIGAN POWER COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106

November 15, 1978

Mr. J.G. Keppler, Regional Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-56  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications  
the following report is submitted:

RO 78-060/03L-0.

Sincerely,

D.V. Shaller  
Plant Manager

/bab

cc: J.E. Dolan  
R.W. Jurgensen  
R.F. Kroeger  
R. Kilburn  
R.J. Vollen BPI  
K.R. Baker RO:III  
R.C. Callen MPSC  
P.W. Steketee, Esq.  
R. Walsh, Esq.  
G. Charnoff, Esq.  
G. Olson  
J.M. Hennigan  
PNSRC  
J.F. Stietzel  
Dir., IE (30 copies)  
Dir., MIRC (3 copies)

**REGULATORY DOCKET FILE COPY**

*Handwritten:* A002  
S/11

7811210 271