

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

② 0 0 0 0 0 0 0 0 0 0 0 0 ③ 4 1 1 1 1 ④ ⑤

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

**REPORT
SOURCE**

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	3	1	5	7	0	3	1	3	7	8	8	0	1	1	6	7	9	9
60	61							68	69						74	75							80
DOCKET NUMBER										EVENT DATE					REPORT DATE								

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING PERFORMANCE OF THE STP.204, CONTAINMENT AIR LOCK LEAKAGE TEST ON THE 650 FOOT
0 3 ELEVATION INNER DOOR, THE DOOR SEAL LEAKAGE RATE EXCEEDED THE LIMIT IDENTIFIED IN
0 4 TECHNICAL SPECIFICATION PARAGRAPH 3.6.1.2. THE TEST WAS STOPPED AND THE SEAL WAS
0 5 INSPECTED AND CLEANED. A RETEST WAS SATISFACTORILY PERFORMED IMMEDIATELY FOLLOWING
0 6 THE ABOVE INSPECTION.
0 7
0 8

SYSTEM CODE S D		CAUSE CODE X	CAUSE SUBCODE Z	COMPONENT CODE P E N T R				COMP. SUBCODE A	VALVE SUBCODE Z
(11)		(12)	(13)	(14)				(15)	(16)
EVENT YEAR 7 8			SEQUENTIAL REPORT NO. 0 2 3		OCCURRENCE CODE / 3	REPORT TYPE X		REVISION NO. _	
(17) LER/RO REPORT NUMBER		(18)	(19)	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0 0 0	ATTACHMENT SUBMITTED N	NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER L
ACTION TAKEN X	FUTURE ACTION X	(20)	(21)	(22)	(23)	(24)	(25)	COMPONENT MANUFACTURER W 3 0 2	
(33)	(34)	(35)	(36)	(37)	(38)	(39)	(40)	(41)	(42)
(43)	(44)	(45)	(46)	(47)	(48)	(49)	(50)	(51)	(52)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

THE CAUSE WAS DETERMINED TO BE PAINT CHIPS WHICH WERE FOUND ON THE RUBBER SEAL AND
APPEARED TO BE OBSTRUCTING THE PROPER SEAL OF THE DOOR. THE CHIPS WERE CLEANED OFF
AND A RETEST WAS PERFORMED. SIGNS ARE BEING CONSTRUCTED WHICH REMIND PERSONNEL TO
INSPECT THE DOOR SEALS UPON EACH OPENING.

FACILITY STATUS (28) 1 5 E 30
 7 8 9
 % POWER 1 0 0 29 13
 10 11 12
 OTHER STATUS NA 44
 METHOD OF DISCOVERY (31) B 31 46
 DISCOVERY DESCRIPTION (32) SURVEILLANCE TEST 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	37	Z	38	NA	39

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1 8	0 0 0	(40)	NA

7901220 117

7		8	9	11		12
				LOSS OF OR DAMAGE TO FACILITY		(43)
			TYPE	DESCRIPTION		
1	9	Z	(42)	NA		

		PUBLICATION			NRC USE ONLY
		ISSUED	DESCRIPTION	(45)	
2	0	N	(44) NA		

NAME OF PREPARER T. P. Beilman

616-465-5901⁶⁸

PHONE:

