

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 0 4 1 6 7 6 8 0 5 0 2 7 9 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 ON 04-02-79 WHILE INVESTIGATING A RELATED INCIDENT IN UNIT TWO, IT WAS DISCOVERED  
0 3 THAT TIME RESPONSE DATA HAD NOT BEEN OBTAINED AS REQUIRED DURING THE APRIL 1976  
0 4 REFUELING OUTAGE FOR A LOW STEAM PRESSURE ESF CHANNEL. THIS IS NOT COMPLIANT WITH  
0 5 THE REQUIREMENTS OF T.S. 4.3.2.1.3, HOWEVER, THE NECESSARY RESPONSE TIMES WERE  
0 6 OBTAINED DURING THE FOLLOWING REFUELING OUTAGE.

0 7  
0 8  
7 8 9 80

0 9 SYSTEM CODE I B 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/RO REPORT NUMBER 7 9 21 22 EVENT YEAR 0 2 5 24 25 SEQUENTIAL REPORT NO. 0 3 28 29 OCCURRENCE CODE L 30 31 REPORT TYPE 0 32 REVISION NO.  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
X 18 X 19 Z 20 Z 21 0 0 0 0 0 23 N 24 N 25 W 1 2 0 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE CHANNEL REQUIRING TIME RESPONSE TESTING WAS INADVERTANTLY OMITTED FROM THE  
1 1 PROCEDURE WHICH IS REVISED PRIOR TO EACH REFUELING OUTAGE. DUE TO THE COMPLEXITY  
1 2 OF EACH REVISION, A CHECKLIST HAS BEEN PREPARED FOR EACH UNIT TO AID APPLICABLE  
1 3 PERSONNEL IN PERFORMING A MORE COMPREHENSIVE REVIEW OF THE PROCEDURE PRIOR TO USE.

1 4  
7 8 9 80

1 5 FACILITY STATUS H 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 ACTIVITY RELEASED Z 33 CONTENT OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER T. P. Beilman

NRC USE ONLY  
68 69 70 71 72 73 74 75 76 77 78 79 80  
PHONE: 616-465-5901



2000  
2000