

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDDC1 200-00000-00 341111 45
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

01 REPORT SOURCE L 605000315 7041379 8050979 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 WHILE PERFORMING HYDRAULIC SNUBBER SURVEILLANCE INSPECTION, SNUBBERS GBD-S573
03 AND GBD-S574 WERE FOUND WITH DRAINED RESERVOIRS. THIS CONSTITUTED A SNUBBER
04 INSPECTION FAILURE PER TECH. SPEC. 4.7.8.1.1, ALTHOUGH SNUBBERS PASSED FUNC-
05 TIONAL TESTING CRITERIA UPON REMOVAL. PUBLIC HEALTH AND SAFETY WERE NOT
06 JEOPARDIZED. NO PREVIOUS EVENTS IDENTICAL TO THIS HAVE OCCURRED.
07

08

09 SYSTEM CODE Z Z 11 CAUSE CODE A 12 CAUSE SUBCODE F 13 COMPONENT CODE S U P O R T 14 COMP. SUBCODE D 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 79 21 22 EVENT YEAR 79 23 24 SEQUENTIAL REPORT NO. 019 25 26 OCCURRENCE CODE 03 27 28 REPORT TYPE L 29 30 REVISION NO. 0 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED N 23 NPD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER I 2 0 7 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 THE DRAINED RESERVOIRS WERE CAUSED BY LOOSE PIPE UNIONS BETWEEN THE SNUBBERS AND
11 THEIR REMOTE RESERVOIRS. THE UNIONS ARE THOUGHT TO HAVE BEEN LOOSENED BY
12 CONTRACTOR PERSONNEL FOLLOWING A PREVIOUS INSPECTION. THE SNUBBERS WERE
13 TESTED AND FOUND TO BE OPERABLE. HOWEVER, THEY WERE REPLACED WITH NEWER MODELS.
14 THE CONSTRUCTION SUPERVISOR WAS NOTIFIED OF THIS EVENT.

15 FACILITY STATUS H 28 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 SURVEILLANCE INSPECTION 32
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION NA 39
7 8 9 10 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION NA 41
7 8 9 10 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION NA 43
7 8 9 10 11 12 80

20 PUBLICITY ISSUED DESCRIPTION NA 45
7 8 9 10 11 12 80

21 NAME OF PREPARER MICHAEL S. BROWN
7 8 9 10 11 12 80

NAME OF PREPARER MICHAEL S. BROWN

PHONE: (616) 465-5901, EXT.398

NRC USE ONLY

10-00