

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	3	1	6	7	0	5	1	9	7	9	8	0	6	0	8	7	9	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	SEE ATTACHED LETTER
---	---	---------------------

0	3	
---	---	--

0	4	
---	---	--

05 _____

0	6	
---	---	--

0	7	
---	---	--

08 |

7 8 9

0	9																		
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE					
F	W	B	A	P	I	P	E	X	X	D	Z								
9	10	11	12	13	14	15	16	17	18	19	20								

(17) LER/RO REPORT NUMBER: 7 9 21 22 23
 SEQUENTIAL REPORT NO.: 0 1 9 24 25 26 27
 OCCURRENCE CODE: 0 1 28 29
 REPORT TYPE: RX 30
 NO.: 31 32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
A			A	A		A		0	3	3	6	Y		Y		A		T	3	3	5
33	18	34	19	35	20	36	21	37			40	41	23	42	24	43	25	44			47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | SEE ATTACHED LETTER

1	1	
---	---	--

1	2	
---	---	--

1	3	
---	---	--

1	4	
---	---	--

7 8 9 FACILITY STATUS 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 5 E 28 1 0 0 29 N/A 30 METHOD OF DISCOVERY 31 A 32 OPERATOR OBSERVATION

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 10 34 N/A

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

N/A

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) N/A	(39)		

7 8 9 11 12 13 80
PERSONNEL INJURIES

NUMBER			DESCRIPTION
1	8	0 0 0	(40) N/A

79 0619 0297

7	8	9	11	12	80
LOSS OF OR DAMAGE TO FACILITY (43)					
TYPE OF DESCRIPTION					

TYPE		DESCRIPTION
1	9	L (42) SMALL LEAKS IN FEEDWATER PIPING TO STEAM GENERATORS.

PUBLICITY	80
ISSUED DESCRIPTION (45)	NRC USE ONLY

2 0 y (44) May 21, 1979, and May 25, 1979.

NAME OF PREPARER D.V. SHALLER

PHONE: (616) 465-5901

Encl. 2
15 -

2

/