

CONTROL BLOCK:

							①
--	--	--	--	--	--	--	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER											25	26	LICENSE TYPE					30	57	CAT	58

CON'T

REPORT SOURCE 01 L 6 0 5 0 0 0 3 1 6 7 0 7 0 2 7 9 8 0 7 3 1 7 9 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | WHILE MAKING A NORMAL UNIT STARTUP, IN MODE 2 AND AT 4% POWER, A SAFETY VALVE
03 | LIFTED ON #3 STEAM GENERATOR. THE REACTOR WAS BROUGHT TO A SUB-CRITICAL CONDITION
04 | BEFORE REACHING 541°F. WHEN TAVG DECREASED TO 532°F THE SAFETY RESEATED. PRIOR
05 | TO RESUMING STARTUP AND TO ALLOW THE SAFETY VALVE TO COOL, THE POWER RANGE HIGH
06 | POWER TRIPS WERE LOWERED TO 85% AND THE SAFETY VALVE WAS GAGGED CONFORMING TO
07 | TECH. SPEC. 3.7.1.1.a.
08 |
7 8 9

SYSTEM CODE H B (11)		CAUSE CODE X (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE V A L V E X (14)		COMP. SUBCODE X (15)		VALVE SUBCODE B (16)	
7 8		9 10		11 12		13 18		19		20	
(17) LER/RO REPORT NUMBER		EVENT YEAR 7 9 (21) (22)		SEQUENTIAL REPORT NO. 0 2 5 (23) (24) (25) (26)		OCCURRENCE CODE / 0 3 (27) (28) (29)		REPORT TYPE L (30)		REVISION NO. 0 (31) (32)	
ACTION TAKEN X (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT B (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 6 (22) (23) (24) (25) (26) (27) (28) (29)		ATTACHMENT SUBMITTED N (30) (31) (32)	
33 34		35 36		37 38 39 40		41 42		43 44		45 46 47	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE SAFETY VALVE OPERATED WITHIN ALLOWED SETPOINTS. AFTER ADEQUATE COOLING THE

1 1 GAG WAS REMOVED AND THE POWER RANGE HIGH POWER TRIPS WERE RESET TO NORMAL.

1 2

1 3

1 4

7 2 0 80

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	C	28	0	0	4	29	NA				30	A	31	OPERATOR OBSERVATION				32
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
ACTIVITY CONTENT				RELEASED OF RELEASE				AMOUNT OF ACTIVITY				LOCATION OF RELEASE							
1	6	Z	33	Z	34	NA				35	NA				36				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
PERSONNEL EXPOSURES				PERSONNEL INJURIES				LOSS OF OR DAMAGE TO FACILITY				PUBLICITY							
NUMBER				NUMBER				TYPE				DESCRIPTION							
1	7	0	0	0	0	0	37	Z	38	NA				39	7908060325				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
PERSONNEL INJURIES				LOSS OF OR DAMAGE TO FACILITY				PUBLICITY				ISSUED							
NUMBER				TYPE				DESCRIPTION				DESCRIPTION							
1	8	0	0	0	0	0	40	NA				41	VERBALLY NOTIFIED LOCAL NEWS MEDIA ABOUT NOISE.						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
LOSS OF OR DAMAGE TO FACILITY				PUBLICITY				ISSUED				NRC USE ONLY							
TYPE				DESCRIPTION				DESCRIPTION				ISSUED							
1	9	Z	42	NA				43	Y				44	VERBALLY NOTIFIED LOCAL NEWS MEDIA ABOUT NOISE.					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
PUBLICITY				ISSUED				NRC USE ONLY				ISSUED							
DESCRIPTION				DESCRIPTION				DESCRIPTION				DESCRIPTION							
2	0	VERBALLY NOTIFIED LOCAL NEWS MEDIA ABOUT NOISE.				VERBALLY NOTIFIED LOCAL NEWS MEDIA ABOUT NOISE.				VERBALLY NOTIFIED LOCAL NEWS MEDIA ABOUT NOISE.									
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	

NAME OF PREPARER C. E. MURPHY

PHONE: (616) 465-5901 X-316