

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8001030833 DOC. DATE: 79/12/31 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME: AUTHOR AFFILIATION
 SHALLER, T.M. Indiana & Michigan Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 KEPPLER, J.G. Region 3, Chicago, Office of the Director

SUBJECT: Confirms 791228 telcon w/D Boyd re four deficiencies discovered during insp under IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." Followup rept will be submitted 800110.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Incident Reports

NOTES: SEND 3 CYS ALL MATL TO ILE

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	05 BC ORB # 1	4		
INTERNAL:	01 REG FILE	1	02 NRC PDR	1
	09 I&E	2	11 MPA	3
	14 TA/EDO	1	15 NOVAK/KNIEL	1
	16 EEB	1	17 AD. FOR ENGR	1
	18 PLANT SYS BR	1	19 I&C SYS BR	1
	20 AD PLANT SYS	1	22 REAC SAFT BR	1
	23 ENGR BR	1	24 KREGER	1
	25 PWR SYS BR	1	26 AD/SITE ANAL	1
	27 OPERA LIC BR	1	28 ACIDENT ANALYS	1
	29 AOX SYS BR	1	E. JORDAN/IE	1
	HANAUER, S.	1	R IRELAND	3
	STS GROUP LEADR	1	TIM H STREET	1
EXTERNAL:	03 LPDR	1	04 NSIC	1
	29 ACRS	16		

JAN 7 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR

54

ENCL

0

ADHI
2

60

DSB



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

December 31, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm our telephone report to your Mr. D. Boyd, Chief of Reactor Projects Section III, at 1615 hours on December 28, 1979.

At that time I informed Mr. Boyd that during analysis of the Unit 2 data gathered in response to IE Bulletin 79-14 four (4) significant non-conformances were identified relative to subject bulletin by our New York office. A brief summary for each of these problems was also read to Mr. Boyd at this time.

A followup report will be submitted by January 10, 1980, as required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller
Plant Manager

/jas

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
R.W. Kilburn
R.E. Masse, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.

G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

A002
5/10

JAN 2 1980
8001030833
8001070 347

\$6
like LER