

Central file

INDIANA & MICHIGAN ELECTRIC COMPANY

P. O. BOX 18
BOWLING GREEN STATION
NEW YORK, N. Y. 10004

January 16, 1980
AEP:NRC:00332

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74

RESPONSE TO IE BULLETIN 79-28

Mr. J. G. Keppler, Regional Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This letter responds to your letter dated December 10, 1979 which transmitted to us IE Bulletin No. 79-28. The required summary of our actions taken in response to this Bulletin at the Donald C. Cook Nuclear Plant Units 1 and 2 follows.

We have determined that NAMCO Model EA180 limit switches were ordered as replacements for use in a safety-related application. None of them had been installed yet. All of them were examined and some were found to have date codes between those cited in the IE Bulletin. We intend to perform the recommended action of replacing the top gasket in the affected switches in accordance with the manufacturer's recommendations. The required gaskets and instructions have been requested from the manufacturer. The proper gaskets will be installed in the identified switches and the conduit hub of each switch with the replacement gasket will be marked with the modification code before the affected switches are released for installation in the plant. The affected switches will remain on hold in the plant storeroom until this work is completed.

These as-yet-to-be-installed NAMCO switches are the only ones existing at the Cook Plant which fall under the action requirements of IE Bulletin No. 79-28.

Very truly yours,

John E. Dolan
John E. Dolan
Vice President

AO 2

JED:em

cc: (Attached)

JAN 18 1980

8001800571 Q

60

Mr. J. G. Keppler

-2-

AEP:NRC:00332

cc: Norman C. Moseley - NRC
R. C. Callen
G. Charnoff
D. V. Shaller - Bridgman
R. S. Hunter
R. W. Jurgensen