

JUN 19 1980

*Central
Files*

INDIANA & MICHIGAN ELECTRIC COMPANY

P. O. BOX 18
BOWLING GREEN STATION
NEW YORK, N. Y. 10004

June 16, 1980
AEP:NRC:00404

Donald C. Cook Nuclear Plant Units 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74

Mr. Harold D. Thornburg
U.S. Nuclear Regulatory Commission
Director of Reactor Construction Inspection, O.I.E.
Washington, DC 20555

Dear Mr. Thornburg:

This letter provides the required response to IE Bulletin
No. 80-09, dated April 16, 1980 and received on April 22, 1980.

Our review of safety-related equipment in Donald C. Cook
Nuclear Plant Units 1 and 2 indicates that ITT General Controls
series AH-90 and NH-90 Hydramotor Actuators are not used in any
safety-related systems or components. Therefore, no further action
is necessary.

Very truly yours,

John E. Dolan
John E. Dolan
Vice President

JED:em

cc: J. G. Keppler - NRC Region III
R. C. Callen
G. Charnoff
D. V. Shaller - Bridgman
R. S. Hunter
R. W. Jurgensen

8007030206 Q

*ADK
2*

GD

