

# INDIANA & MICHIGAN ELECTRIC COMPANY

P. O. BOX 18  
BOWLING GREEN STATION  
NEW YORK, N. Y. 10004

*Control  
JMS*

December 17, 1980  
AEP:NRC:0493

Donald C. Cook Nuclear Plant Units Nos. 1 and 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74  
Valve Yokes Supplied by Malcolm Foundry Company (IE Bulletin No. 80-21)

Mr. James G. Keppler, Regional Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region III  
Glen Ellyn, Illinois 60137


Dear Mr. Keppler:

This letter provides our response to IE Bulletin No. 80-21. On December 5, 1980, an extension request was made to the NRC Region III Office on our response to IE Bulletin No. 80-21 and a two week extension was granted by Mr. Duane C. Boyd.

A review has been performed on valves which are being used or planned for use in safety related systems at the D. C. Cook facility in accordance with Action Item No. 1 of the subject bulletin. Written documents have been received from valve manufacturers who supplied the valves. These documents indicate that none of the valves employed yokes cast by Malcolm Foundry Company, Inc.

In consequence of the above, action items 2 and 3 are not applicable to the Donald C. Cook Nuclear Plant.

Very truly yours,

  
R. S. Hunter  
Vice President

cc: R. C. Callen  
G. Charnoff  
D. V. Shaller - Bridgman  
John E. Dolan  
R. W. Jurgensen  
NRC Resident Inspector at Cook Plant - Bridgman  
H. D. Thornburg - NRC

*AO 2 -*

DEC 22 1980

*Q* 8101120315

