

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8105120365 DOC. DATE: 81/05/05 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME: AUTHOR AFFILIATION
 WIZNER, D.G. Indiana & Michigan Electric Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 81-010/03L-0: on 810411, snubbers 1 & 29 were found inoperable. Caused by fluid leak on 29 due to separation of joint at end seal O-ring. O-ring replaced. Snubber 1 upside down due to lose extension rod locknut. Locknut tightened..

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5
 TITLE: Incident Reports

NOTES: Send 3 copies of all material to I&E. 05000316

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	VARGA, S. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	AEOD/DMU	3	3
	ASLBP/J. HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR, ENGINEERI20	1	1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	1	1	JORDAN, E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	NRC PDR 02	1	1
	OR-ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 64 ENCL 64

[illegible]