


DmB



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

TEHQ FILE COPY

January 6, 1984

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58/DPR-74
Docket Nos. 50-315/50-316

Dear Mr. Keppler:

Pursuant to the requirements of Appendix B, Part II, Nonradiological, Environmental Protection Plan, Section 3.2, a copy of the report to the Michigan Water Resources Commission notifying them of the failure to take the Steam Generator blowdown samples for total suspended solids, iron and copper, is attached. This report is required by Amendment No. 54 to Facility Operating License No. DPR-58 and Amendment No. 40 to Facility Operating License No. DPR-74 dated May 6, 1982.


Sincerely,


W.G. Smith, Jr.
Plant Manager

/bab

Attachment

cc: John E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E.R. Swanson, RO:III
R.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan


INPO
Dir., IE (40 copies)
Dir., MIPC (4 copies)
PNSRC
J.F. Stietzel
E.L. Townley
K.R. Baker
R.O. Bruggee, EPRI

8401130336 840106
PDR AD0CK 05000315
S PDR

JAN 9 1984

IE0111

UNITED STATES

DEPARTMENT OF JUSTICE

OFFICE OF THE ATTORNEY GENERAL

WASHINGTON, D. C.

1944

MEMORANDUM FOR THE ATTORNEY GENERAL

FROM: [illegible]

SUBJECT: [illegible]

[illegible text]

[illegible text]

[illegible text]

[illegible text]


[illegible text]

[illegible text]

[illegible text]

[illegible text]

[illegible text]



INDIANA & MICHIGAN ELECTRIC COMPANY

ONE SUMMIT SQUARE, P. O. BOX 60, FORT WAYNE IN. 46801
Telephone: (219) 425-2111

RICHARD C. MENGE
Vice President

December 12¹, 1983

Mr. Paul D. Zugger
Executive Secretary
Michigan Water Resources Commission
Stevens T. Mason Building
Box 30026
Lansing, MI. 48909

Re: Donald C. Cook Nuclear Plant
NPDES Permit No. MI 0005827
Steam Generator Blowdown

Dear Mr. Zugger:

A review of the November NPDES monitoring report revealed that a sample of "Steam Generator Blowdown Prior to Mixing Cooling Water" was not obtained for total suspended solids or Iron and Copper analysis.

Upon investigation, it was found that with Nuclear Reactor Unit #2 in the start-up mode, the laboratory technician mistakenly thought that suspended solids and Iron and Copper samples were only to be taken in the normal running mode.

The sampling procedure has been reviewed with the technician.

Very truly yours,

R. C. Menge
Vice President

RCM/be
cc: W. G. Smith

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents; and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

R. C. Menge

bc: R. W. Jurgensen
T. A. Kriesel
J. A. Wojcik
R. W. Reeves/C. E. Hawk
J. P. White
R. E. Zahler