

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8911130126 DOC. DATE: 89/11/06 NOTARIZED: NO DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH. NAME AUTHOR AFFILIATION:  
 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP. NAME RECIPIENT AFFILIATION  
 MURLEY, T.E. Document Control Branch (Document Control Desk)

SUBJECT: Submits Suppl 1 to response to NRC Bulletin 88-010  
 "Nonconforming Molded Case Circuit Breakers."

DISTRIBUTION CODE: IE21D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3  
 TITLE: Bulletin Response 88-10 - Nonconforming Molded Case Circuit Breakers. D

## NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-1 LA	1 0	PD3-1 PD	1 1
GIITTER, J.	1 1		
INTERNAL: AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
NRR DOEA/GCB 11	1 1	NRR GILL, A.S.	1 1
NRR GUILLEN, J	1 1	NRR POTAPOUS, U	1 1
NRR STONE, J.C.	1 1	NRR/DEST/ADS 7E	1 1
NRR/DEST/MEB 9H	1 1	NRR/DOEA/EAB 11	1 1
NRR/DOEA/GCB 11	1 1	NRR/DREP/EPB 10	1 1
NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
<del>REG FILE</del> 02	1 1	RES/DSIR/EIB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 22

*AC*  
*11/11/89*



AEP:NRC:1083E

Donald C. Cook Nuclear Plant Units 1 and 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74  
NRC BULLETIN NO. 88-10, SUPPLEMENT 1: NONCONFORMING MOLDED-CASE  
CIRCUIT BREAKERS (BULLETIN RESPONSE SUPPLEMENT)

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Attn: T. E. Murley

November 6, 1989

Dear Dr. Murley:

The purpose of this letter is to supplement one of our prior responses to Bulletin No. 88-10. Attachment 3 of AEP:NRC:1083A, "NRC Bulletin No. 88-10: Report on Action Item Status," dated May 16, 1989, provided information on molded-case circuit breakers installed in Unit 1 that could not be traced to the circuit breaker manufacturer. Per Bulletin No. 88-10 requirements, our initial review of installed molded-case circuit breakers was limited to circuit breakers installed after August 1, 1983. As stated in AEP:NRC:1083A, the molded-case circuit breakers listed in Attachment 3 of that submittal were identified by reviewing design change documentation, stores issue records, and job orders.

NRC Position 4 of NRC Bulletin No. 88-10, Supplement 1 states that appropriate corrective actions as required by 10 CFR Part 50, Appendix B should be taken if an addressee identifies any circuit breakers as nontraceable during the review requested by Bulletin No. 88-10. Appropriate corrective actions include an assessment of the acceptability of all installed safety-related circuit breakers that were procured under the same purchase orders as the nontraceable circuit breakers.

We expanded the scope of our procurement records review to include molded-case circuit breakers purchased between January 1, 1979, and August 1, 1983. Purchase orders for molded-case circuit breakers ordered before 1979 were considered original Cook Nuclear Plant construction purchase orders which are not included in the scope of NRC Bulletin No. 88-10 or Supplement 1.

Dr. T. E. Murley

-2-

AEP:NRC:1083E


Our review of circuit breaker purchases between January 1, 1979, and August 1, 1983, revealed a single nontraceable safety-related circuit breaker installed in Unit 1. No nontraceable safety-related circuit breaker Unit 2 installations, beyond those previously reported, were identified. Therefore, the following information is submitted to supplement AEP:NRC:1083A Attachment 3 regarding the additional Unit 1 nontraceable circuit breaker:

Manufacturer	- Westinghouse
Model Number	- FB3100
Procurement Source	- WESCO, Ft. Wayne, IN
Quantity	- 1
System	- Backup ventilation (technical support center)

The above circuit breaker has been replaced with a traceable spare.

This letter is being submitted under oath pursuant to the provisions of Section 182a, Atomic Energy Act of 1954, as amended.

Sincerely,




M. P. Alexich  
Vice President

ldp

cc: D. H. Williams, Jr.  
A. A. Blind - Bridgman  
R. C. Callen  
G. Charnoff  
A. B. Davis - Region III  
NRC Resident Inspector - Bridgman  
NFEM Section Chief

STATE OF OHIO)  
COUNTY OF FRANKLIN)

Milton P. Alexich, being duly sworn, deposes and says that he is the Vice President of licensee Indiana Michigan Power Company, that he has read the foregoing Response to NRC Bulletin No. 88-10, Supplement 1: Nonconforming Molded-Case Circuit Breakers (Bulletin Response Supplement) and knows the contents thereof; and that said contents are true to the best of his knowledge and belief.



Subscribed and sworn to before me this 6th

day of June, 1989.



NOTARY PUBLIC

RITA D. HILL  
NOTARY PUBLIC STATE OF OHIO  
MY COMMISSION EXPIRES 6-28-94