

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9903250369 DOC.DATE: 99/03/18 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME ' AUTHOR AFFILIATION
POWERS,R.P. Indiana Michigan Power Co.
RECIP.NAME RECIPIENT AFFILIATION
. Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-005-00, reactor trip breaker manual
actuators during rod drop testing not previously reported.
Listed commitments identified in submittal.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 1
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES :

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD3-3 PD		1	1		STANG, J		1	1
INTERNAL:	AEOD/SPD/RAB		2	2		AEOD/SPD/RRAB		1	1
	FILE CENTER		1	1		NRR/DRCH/HOHB		1	1
	NRR/DRCH/HOMB		1	1		NRR/DRPM/PECB		1	1
	NRR/DSSA/SPLB		1	1		RES/DET/EIB		1	1
	RGN3 FILE 01		1	1					
EXTERNAL:	L ST LOBBY WARD		1	1		LMITCO MARSHALL		1	1
	NOAC POORE, W.		1	1		NOAC QUEENER, DS		1	1
	NRC PDR		1	1		NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 18

Indiana Michigan
Power Company
Cock Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5501



March 18, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-005-00, "Reactor Trip Breaker Manual Actuations During Rod Drop Testing Not Previously Reported."

The following commitment has been identified in this submittal:

- The root cause investigation for this event has not been completed. Based on the results of this investigation, additional corrective actions, including preventive actions may be developed. It is anticipated that, if significant changes are identified, supplemental information regarding corrective and preventive actions will be provided in an update to this LER.

Sincerely,

A handwritten signature in dark ink, appearing to read 'R. P. Powers', with a long horizontal stroke extending to the right.

R. P. Powers
Vice President

/mbd
Attachment

c: J. E. Dyer, Region III
P. A. Barrett
D. F. Kunsemiller
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

9903250369 990318
PDR ADOCK 05000315
S PDR

Handwritten notes: '11' and 'IE 22'.

Vertical text on the right margin: '3-18-99'.

